


434 Bomb Wing - October 1968

B/WB CARRIAGEIZATION



SOURCE: HCS: 1-CAC-082
AF Form 991

438 East Wing - October 1968


DATE OF DEMONSTRATION

The following is a list of items cannibalized showing the number of times and the reason for cannibalization:

ITEM	REASON	NUMBER OF TIMES	REASON FOR DEMONSTRATION
2995-23-665FL	To Prevent NONG	1	0
1966-42-454AZ	To Prevent WROG	1	0
668-47-8977	To Prevent NONG	1	0
166-77-0166	To Prevent NONG	1	0
473-65-0917	To Prevent NONG	1	0
240-77-3407EL	To Prevent NONG	1	0
2995-14-8629	To Prevent NONG	1	0
1966-71-744AZ	To Prevent NONG	1	0
163-72-521	To Prevent NONG	1	0
2915-87-833FL	To Prevent NONG	1	0
2995-70-235FL	To Prevent NONG	1	0
6215-25-0380	To Prevent NONG	1	0
166-77-4040	To Prevent NONG	1	0
601-65-0030	To Prevent NONG	1	0
2895-40-5374MB	To Prevent NONG	1	0

434 Bomb Wing - October 1968

MC-135 CANNIBALIZATIONS



SOURCE: RDS: 1-840-082
AF Form 991

43d Bomb Wing - October 1948


REPAIRS

The following is a list of items manufactured showing the number of items and the reason for manufacturing:

ITEM	REASON	ITEMS ORDERED	REASON FOR FAILURE
593-481-2757	Detector	1	0
156-450-4236	RT-104	1	0
593-481-6694	Switch	1	0
6610-157-3071	Masterer	1	0
5941-401-4952	RT-274	1	0
593-481-6694	Switch	1	0

43d Bomb Wing - October 1968

TREND OF REPEAT WHITE-IPS B-58



SOURCE: SAC Form 128 and 126-1

Total write-up averaged 6 per sortie.

434 Bom. Wing - October 1968

REPEATS BY SYSTEM

1. There were 145 sorties flown with repeats occurring on 64 sorties. They range from 1 to 4 per sortie as follows:

- 1 Repeat on 29
2 Repeats on 20
3 Repeats on 3
4 Repeats on 2

2. The reliability code distribution on the repeats was 53 code 2 and 43 code 3. The distribution of the repeats by system are as follows:

SYSTEM	CODE 2	CODE 3	SYSTEM	CODE 2	CODE 3	SYSTEM	CODE 2	CODE 3
Engine	1	0	Explosive	3	10	Autopilot	4	1
A/C Engine	1	0	ARM	22	3	IFF Radio	1	1
HYD/FAEU	1	0	BM Bar	2	0	Comms	1	1
Airframe	2	0	P. . . Beacon	1	0	Star Alt	1	1
HF Radio	0	1	Airburster	1	0	Fls	1	0
IFF	0	1	Slam For Sigs	1	0	ECG	1	0
Compass	2	1	Fuel (Other)	0	0	ECM Trans	1	0

3. There were 14 repeat code 3 that were code 2 on the previous sortie. These repeats were on the following systems:

SYSTEM	REPEATS	SYSTEM	REPEATS
Autopilot	1	IFF	1
Tacan	1	Comms	1
Doppler	4	Nav	1
Flar	3	ECM Radar	1

4. There were 27 repeat code 3 that were code 3 on the previous sortie. These repeats are on the following systems:

SYSTEM	REPEATS	SYSTEM	REPEATS
HF Radio	1	IFF Radio	1
Radar Alt	2	Doppler	11
Elec Per Supply	1	Nav	5
ECG Radar	1	ECM Trans	6

5. The repeats followed the normal system pattern with most going to the electronic area. This is the case in both code 2 and code 3 repeats.

4th Bomb Wing - October 1968

WORK CENTER	MANHEUR UTILIZATION							TOTAL
	B-58	F0B	KG-123	EF7K	AGE	SUPPLY	OTHER	
SHOP								
TB Maint Team	1,760	1,174						2,934
102 Team #2	2,032	3						2,035
103 Team #3	2,032	28						2,060
104 Team #4	1,076	28						1,104
105 Team #5	1,076	31						1,107
106 Team #6	2,032	30						2,062
107 Team #7	1,352	15						1,367
108 Tanker Team #1	7	1						8
111 Tanker Team #11	1	1						2
185 Non Par AGE	2,032							2,032
188 Phase Team	2,032							2,032
310 Fixed Wg A/C	6							6
311 Helicopter	1							1
320 Transient	12							12
Total	13,722	2,811						16,533
24110 Radio	1,344							1,344
120 Radar	1,076	23						1,099
125 Doppler	1							1
131 BM Shop	1,076							1,076
210 Fire Control	1,076							1,076
210 Bomb Nav	6,563							6,563
330 Flt Control	1,076							1,076
331 KC Antipilot								
400 Photo	411							411
500 FUEL								
TOTAL	12,222	2,110						14,332
TOTAL WING	5,974	6,000	1776	637	1934	468	586	16,779


SOURCE: Report 3-1 on AFPO Form 307-2 The figures portrayed indicate the labor hours as detailed

4th Bomb Wing - October 1968

WORK CENTER	MANHOURL UTILIZATION							TOTAL
	E-58	POB	NO-135	H-1R	AGE	SUPPLY	OTHER	
22110	774	10	12	8	82	159	1149	
120	17	14	12	16	44	139	227	
130	2662	4	24	27	5	17	2739	
150								
155								
160								
170	41						41	
210								
220								
230								
210								
320								
330								
340								
350								
360								
370								
380								
390								
400								
410								
420								
430								
TOTAL	22164	48	2742	143	208	298	29793	
22110	2444	747	8			175	3274	
120	11	1639			27	253	2800	
210	35	1148			110	236	2529	
220						421	421	
250					128		128	
TOTAL	2495	2594	14		193	605	5801	

434 Post Wing - October 1968

E-2 TIRE FOD



FOD RATE

HOW MALFUNCTION	DEC	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT
020 WORN	139	81	145	133	177	177	167	144	159	159	158
111 BURST	0	0	8	7	1	0	0	0	0	0	0
OTHER	23	8	18	19	22	6	12	13	17	17	17
(FOD) 116 CUT	131	94	109	103	66	52	76	81	86	101	113
(FOD) 540 PUNCTURED	0	0	0	0	0	0	0	1	1	1	0
TOTAL	293	184	370	363	266	236	276	245	263	278	291
TOTAL FOD	171	94	109	103	66	52	76	81	86	101	113
SORTIES FLOWN	136	180	177	177	180	225	210	202	221	211	179
FOD RATE	.68	.52	.62	.58	.37	.23	.36	.40	.39	.48	.63
SOURCE: MOC RPT #5											

The number of tire changes decreased slightly during the month of October. Increases were noted in FOD, "BURST", and "OTHER" while there was a decrease in tires "WORN". The prime cause for the higher rate of .26 was due to a 61% increase in "CUT" tires.

FORWARD

AJ Smith King

- 1. This Maintenance Summary is analyzed and prepared each month by the Analyst assigned to the Deputy Commander for Maintenance at Norwood Air Station, CA, CA, USAF.
- 2. This summary is prepared for use of local maintenance agencies and if necessary will be forwarded to the Director of local headquarters. Maintenance operations are listed in this summary because it is to be included in this summary, unless any other special instructions apply to operations in the following areas:
- 3. Maintenance of the maintenance system. This report lists areas to be inspected. Reports are prepared, submitted, and filed. The maintenance personnel are given the date and all areas of the MOC system.
- 4. Maintenance of the maintenance system. This report lists areas to be inspected. Reports are prepared, submitted, and filed. The maintenance personnel are given the date and all areas of the MOC system.
- 5. Maintenance of the maintenance system. This report lists areas to be inspected. Reports are prepared, submitted, and filed. The maintenance personnel are given the date and all areas of the MOC system.
- 6. Maintenance of the maintenance system. This report lists areas to be inspected. Reports are prepared, submitted, and filed. The maintenance personnel are given the date and all areas of the MOC system.
- 7. The above listing reflects the broad areas of area available. If an analysis or study on the above or any subject relating to the maintenance effort is desired, contact COM Analysts.

James D. Fickett
 JAMES D. FICKETT, USAF
 Deputy Commander, Main Force

434 Bomb King - November 1

DESCRIPTION

3-50000 MG	2	43PWS	5
825M	2	43AMS	5
43E	1	27000	3
4300N	1	EMII	1
43000	1	3010-AP	1
4300R	1	3010 FTD	1
4300MA	5	3800MA	1
4300MT	1	GE (PMS)	1
4300M086	1	PD 88	1
4300M	1	430 HISTORIAN	1
4300NS	1	4300TFS	4
4300S	5		1

434 Bomb Wing - November 1968

TABLE OF CONTENTS

Foreword	3
SAC Form 421 - 01 Manhours Per Service	4
SAC Form 473 - Maintenance Production on Aircraft	6
SAC Form 509/509a - Base Self Sufficiency	12
B-58 Accomplishments	14
TU-98 Accomplishments	16
Bomber Aircraft & Maintenance Team Utilization	18
KC-135 Accomplishments	19
B-58 Tire FOD	20
Engine Shutdowns - J-57/J-79	22
KC-135 NORM	24
B-58 NORM	26
B/TB Cannibalization	28
KC-135 Cannibalization	30
Repeat Write-Ups - B-58	32
Manhour Utilization	32

01 MANHOURS PER SORTIE/HOUR		PREVIOUS MONTH	PRECEDING MONTH	CURRENT MONTH	ORGANIZATION	REPORTING P
<p>I. BOMBER B/7B-58</p>						
WING	20.6	20.3	20.3	20.3	<p>NOTE: The manhours per sortie and flying hour decreased during November. The prime cause for this was a decrease in the number of AFIO AFI's processed for the aircraft and an increase in maintenance time employed.</p>	<p>November</p>
OWS	91.8	89.8	89.8	89.8		
ACAB	21.1	20.4	20.4	20.4		
PAW	10.4	10.4	10.4	10.4		
ACAB	21.1	20.4	20.4	20.4		
<p>TANKER KC-135</p>						
WING	12.1	12.1	12.1	12.1	<p>NOTE: Manhours expended on supply and other activities non-identifiable to aircraft were not used in computation, although they were in support and distributed without:</p>	<p>998 1176 378 482</p>
OWS	47.2	47.2	47.2	47.2		
ACAB	14.2	14.2	14.2	14.2		
PAW	14.2	14.2	14.2	14.2		
<p>II. 01 MANHOURS PER FLYING HOUR</p>						
<p>BOMBER B/7B-58</p>						
WING	6.6	6.6	6.6	6.6	<p>NOTE: The overall cost per sortie increased during November as compared with October. Although there was a decrease in sorties flown, cost per flying hour slightly increased with a decrease in the total number of flying hours.</p>	<p>998 1176 378 482</p>
OWS	21.6	21.6	21.6	21.6		
ACAB	25.2	25.2	25.2	25.2		
PAW	25.2	25.2	25.2	25.2		
<p>TANKER KC-135</p>						
WING	28.8	28.7	28.7	28.9	<p>NOTE: The overall cost per sortie increased during November as compared with October. Although there was a decrease in sorties flown, cost per flying hour slightly increased with a decrease in the total number of flying hours.</p>	<p>998 1176 378 482</p>
OWS	11.7	12.1	12.1	12.1		
ACAB	2.2	2.2	2.2	2.2		
<p>HARRATIVE</p>						
WING	14.5	14.5	14.5	14.5		

MAINTENANCE PRODUCTION ON AIRCRAFT					ORGANIZATION	REPORTING PERIOD
					434 Bomb Wing	November 1968
					REMARKS	
TYPE AIRCRAFT	NO-135	SEP	OCT	NOV		
AIRCRAFT POSSESSED		18.1	16.7	13.8	Possessed aircraft are based on hours reported in the MAI-41 Report. Possessed aircraft decreased due to dropping possession on deployed aircraft. Of the 78 sorties flown, 6 were launched away from the home station.	
AIRCRAFT AVAILABLE		8.3	8.0	9.3		
SORTIES FLOWN		107	91	98		
SORTIES PER AVAIL AIRCRAFT		12.9	10.2	8.4		
HOURS FLOWN		451	447	424		
HOURS PER AVAIL AIRCRAFT		51.2	50.2	41.6		
RECOVERY TIME (Average)		2.3	2.3	2.3		
TIME TO OR (Average)						
TYPE AIRCRAFT					REMARKS	
AIRCRAFT POSSESSED						
AIRCRAFT AVAILABLE						
SORTIES FLOWN						
SORTIES PER AVAIL AIRCRAFT						
HOURS FLOWN						
HOURS PER AVAIL AIRCRAFT						
RECOVERY TIME (Average)						
TIME TO OR (Average)						

MAINTENANCE PRODUCTION ON AIRCRAFT				ORGANIZATION	REPORTING
				433 38th AFB	November 1964
				REMARKS	
SORTIE PRODUCTION		PREVIOUS	LAST	<p>Forecasted aircraft are based on hours reported in the MAP-41 report. Forecasted and available aircraft are in Dept. Modification Approval/Reports.</p> <p>Of the 121 sorties flown, 12 were cancelled away from the base station. These were primarily weather diverted return sorties and ferry sorties from modification.</p> <p>Overall sortie production was affected by 23 cancellations, with 1 for material reasons.</p>	
TYPE AIRCRAFT	F-4E	587	573		
AIRCRAFT POSSESSED	34.1	34.0	34.0		
AIRCRAFT AVAILABLE	34.1	34.0	34.1		
SORTIES FLOWN	121	115	118		
SORTIES PER AVAIL AIRCRAFT	3.5	3.4	3.5		
HOURS FLOWN	708	673	685		
HOURS PER AVAIL AIRCRAFT	20.8	19.8	20.1		
RECOVERY TIME (AIRMAN)	2.4	2.4	2.4		
TIME TO OR (AIRMAN)					
TYPE AIRCRAFT	F-4E				
AIRCRAFT POSSESSED	34.0	34.0	34.0		
AIRCRAFT AVAILABLE	34.0	34.0	34.0		
SORTIES FLOWN	58	62	47		
SORTIES PER AVAIL AIRCRAFT	1.7	1.8	1.4		
HOURS FLOWN	138	159	128		
HOURS PER AVAIL AIRCRAFT	4.0	4.7	3.8		
RECOVERY TIME (AIRMAN)					
TIME TO OR (AIRMAN)					
				REMARKS	
				Forecasted aircraft are based on hours reported in MAP-41 Report.	
				Sortie production was affected by 23 cancellations, with 27 for material reasons and 1 for supply.	

WORK CENTER	BASE SELF SUFFICIENCY													WING			SQUADRON			DATE										
	SELF SUFFICIENCY EVALUATION CODES													4-9th Bomb Wing			November 1968													
	REPAIR CODES													MRTS CODES			TOTAL PROCESSED													
	A	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z	TOTAL REPAIR	TOTAL MRTS	TOTAL PROCESSED	PREVIOUS MONTH	LAST MONTH	CURRENT MONTH		
MMS	1027	217	11	123	29																	1429	25	1454	98.5	98.4	98.2			
AMS	428	295	6	37																		763	43	812	94.6	94.2	94.3			
FLY SIMULATOR																														
MMS	1	1																				2	2	2	100.0	100.0	100.0			
WING TOTAL	1463	513	17	160	29																	2228	74	2302	98.2	98.0	98.2			
REMARKS	The overall wing repair rate continues to decrease; 9% in October, 9.7% in November. Contributing factors were; a. reduction in repair actions and a high level of MRTS actions, especially in Code 4 - Bench Checked - MRTS - Lack of Parts. Special emphasis, especially the lack of bits and pieces is being evaluated to pinpoint supply bottlenecks.																													

SHOP ACTIONS TAKEN		SQUADRON												DATE							
		ACTION TAKEN CODES																			
		B	C	D	E	J	M	N	P	Q	R	S	T	U	V	W	X	Y	Z	1	
1	ARK CENTER																				
2	FMS																				
3	APMS																				
4	ELT																				
5	ELT																				
6	MMG																				
7	MMG																				
8	MMG																				
9	MMG																				
10	MMG																				
11	MMG																				
12	WING TOTAL																				
13	WING TOTAL																				
14	WING TOTAL																				
15	WING TOTAL																				
16	WING TOTAL																				
17	WING TOTAL																				
18	WING TOTAL																				
WORK CENTER		CODE B %												CODE I %	REMARKS						
1	FMS	PREVIOUS MONTH	LAST MONTH	CURRENT MONTH	PREVIOUS MONTH	LAST MONTH	CURRENT MONTH	PREVIOUS MONTH	LAST MONTH	CURRENT MONTH	PREVIOUS MONTH	LAST MONTH	CURRENT MONTH	PREVIOUS MONTH	LAST MONTH	CURRENT MONTH	PREVIOUS MONTH	LAST MONTH	CURRENT MONTH	REMARKS	
2	FMS	6.6	7.7	8.8	10.0	11.2	12.4	13.6	14.8	16.0	17.2	18.4	19.6	20.8	22.0	23.2	24.4	25.6	26.8	An improvement was noted in two areas; code B, bench checked-serviceable (no repair required) and code C - bench checked - repaired before.	
3	APMS	11.2	12.4	13.6	14.8	16.0	17.2	18.4	19.6	20.8	22.0	23.2	24.4	25.6	26.8	28.0	29.2	30.4	31.6	Code B actions:	
4	ELT	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	Firebrault: 45AMP Glass, Thermal Repair	
5	ELT	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	45AMP Reservoir, Utility Valve	
6	MMG	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	45AMP Glass, Thermal Repair	
7	MMG	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	45AMP Reservoir, Utility Valve	
8	MMG	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	45AMP Glass, Thermal Repair	
9	WING TOTAL	3.95	4.5	4.8	5.4	6.0	6.6	7.2	7.8	8.4	9.0	9.6	10.2	10.8	11.4	12.0	12.6	13.2	13.8	45AMP Glass, Expansion	
10	WING TOTAL																				45AMP Coupling, Self-seal.
11	WING TOTAL																				45AMP Glass, Expansion
12	WING TOTAL																				45AMP Coupling, Self-seal.
13	WING TOTAL																				45AMP Glass, Expansion
14	WING TOTAL																				45AMP Coupling, Self-seal.
15	WING TOTAL																				45AMP Glass, Expansion
16	WING TOTAL																				45AMP Coupling, Self-seal.
17	WING TOTAL																				45AMP Glass, Expansion
18	WING TOTAL																				45AMP Coupling, Self-seal.

SAC Rep on 20th Previous edition is obsolete.

NAV-6179, 11/1959

SHOP ACTIONS TAKEN		MONTHS												ACT. TAKEN / DEF.	REMARKS												
WORK CENTER		B	C	D	E	F	G	H	I	J	K	L	M			N	O	P	Q	R	S	T	U	V	W	X	Y
1	23110 Mach Shop																										
2	23120 Welding																										
3	23130 Sheet Rep																										
4	23140 Sheet Shop																										
5	23150 Sheet Cont																										
6	23160 Sheet Cont																										
7	23170 Aero Rep																										
8	23180 Fuel Sys																										
9	23190 Weld																										
10	23200 Weld																										
11	23210 Instrument																										
12	23220 M/T																										
13	23230 Wire																										
14	23240 IFR																										
15	23250 Eryous																										
16	23260 Air																										
17	23270 Hyd																										
18	Shop Total	0.6	0.8	1.1	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	
19																											
20																											
21	23280 Mach Shop	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
22	23290 Reading	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	
23	23300 Sheet Rep	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
24	23310 Sheet Equip	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
25	23320 Sheet Cont	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
26	23330 Instrument	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
27	23340 Aero Rep	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
28	23350 Fuel Sys	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
29	23360 Weld	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
30	23370 Weld	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
31	23380 Instrument	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	
32	23390 M/T	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
33	23400 Wire	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
34	23410 IFR	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
35	23420 Eryous	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
36	23430 Hyd	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
37	Shop Total	0.6	0.8	1.1	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2	
38																											
39																											

A marked reduction in code 8 - bench checked - repair referred has been acted, i.e., 141 recorded in October, 28 in November. The Electric and Pneumatic Shops showed the greatest improvement, although they are still faced with a parts shortage. Code 8 - Bench checked returned to depot facility by direction of system or item manager. #Units 4
23340-Pneu W/C

WING CENTER	BASE SELF SUFFICIENCY					WING	43730					DATE	November 1968		
	SELF SUFFICIENCY EVALUATION CODES						SQUADRON	TOTAL NRTS	TOTAL PROCESSED	SELF SUFFICIENCY RATE			LAST MONTH	CURRENT MONTH	
	A	F	G	K	L					Z	PREVIOUS MONTH				LAST MONTH
2011															
2012															
2013															
2014															
2015															
2016															
2017															
2018															
2019															
2020															
2021															
2022															
2023															
2024															
2025															
2026															
2027															
2028															
2029															
2030															
2031															
2032															
2033															
2034															
2035															
2036															
2037															
2038															
2039															
2040															

REMARKS
 The overall squadron's base self sufficiency rate, as with PMS, has been effected by a reduction in items repaired and a constancy in NRTS action.

SHOP ACTIONS TAKEN		BING	424 Bomb Wing		SQUADRON	424B-C							DATE							
WORK CENTER		B	C	D	E	J	M	N	P	Q	R	S	T	U	V	W	X	Y	Z	
		PREVIOUS MONTH	LAST MONTH	CODE B %	CURRENT MONTH	PREVIOUS MONTH	LAST MONTH	CODE 1 %	CURRENT MONTH	PREVIOUS MONTH	LAST MONTH	CODE 1 %	CURRENT MONTH	REMARKS						
1	24110 Radio	10.1	9.4	9.4	10.3	11.2	9.1	9.0	10.0	11.2	9.1	9.0	10.0							
2	24120 Radar	9.9	10.7	10.7	2.8	3.1	6.1	6.6	6.6	3.1	6.1	6.6	6.6							
3	24130 ERM CBP	18.9	18.2	18.2	28.4	18.9	21.8	27.0	27.0	18.9	21.8	27.0	27.0							
4	24200 Fire Cont	0.0	0.0	0.0	0.0	6.2	16.4	12.8	12.8	6.2	16.4	12.8	12.8							
5	24300 Bomb Bay	1.5	1.0	1.0	17.8	21.2	21.1	21.2	21.2	21.2	21.1	21.2	21.2							
6	24330 Flt Cont	0.0	1.0	1.0	69.8	61.7	76.3	76.3	76.3	61.7	76.3	76.3	76.3							
7	24530 Antiplot	0.0	3.2	3.2	0.0	54.8	78.7	58.2	58.2	54.8	78.7	58.2	58.2							
8	24700 Photo	7.1	0.0	0.0	4.4	14.3	33.3	17.4	17.4	14.3	33.3	17.4	17.4							
9	24750 PMEL	0.0	0.0	0.0	0.0	0.0	51.1	0.0	0.0	0.0	51.1	0.0	0.0							
10	24125 Doppler	0.0	35.2	35.2	8.7	8.2	17.7	34.8	34.8	8.2	17.7	34.8	34.8							
11																				
12																				
13	Squad Total	10.2	10.7	10.7	11.8	19.9	21.6	22.0	22.0	19.9	21.6	22.0	22.0							
14																				
15																				
16																				
17																				
18																				
REMARKS		<p>No significant trends noted.</p> <p>Code 8 - Bench checked returned to depot facility by direction of systems or item manager W/C #bits 24310-Bomb/Bay 1</p>																		

434 Bomb Wing - November 1948

B-28 SCHEDULE EFFECTIVENESS AND ACCOMPLISHMENTS

1. The information that follows is extracted from the I-CAC-002 Report and reflects the B-28 activity for November and the preceding 6 months.

	MAY	JUN	JUL	AUG	SEP	OCT	NOV
Sorties Scheduled	162	142	150	128	128	165	137
Sorties Cancelled	18	10	10	14	13	34	21
Sorties Added	7	7	9	15	6	11	15
Sorties Airborne	141	139	149	159	121	145	131
Sorties Early/Late	17	15	10	11	15	13	19
Sorties On Time	124	124	139	148	106	132	112
Air Aborts	4	4	6	6	2	5	2
Hours Flown	871	738	822	1010	768	893	842
Average Sortie Length	7.0	5.3	6.4	6.4	5.9	6.8	6.4

2. The schedule deviation causes for November were:

	ARR	LAC	DAYX	TOTAL
Alert	4	6	2	12
Weather	3	3	1	7
FAA	5	8	9	22
Operations	3	1	20	24
Material	1	1	1	3
Receiver/Tanker	2	1	6	9
CAC	15	19	21	55
Total	48	68	76	192

3. Material deviations for November by system:

	LTO	DAYX	AIR	ARR	TOTAL
Air Frame	1	2			3
Air Conditioning	3	1	1		5
Flight Control	2	1	1		4
Power Plant	1				1
Elect Pwr Supply	2	1			3
Fuel System	1				1
Interphone	1		1		2
Hydraulics	1				1
Support General	8	9	4		21
Total	24	13	2		39

434 Bomb Wing - November 1952

4. The 9 material cancellations by cause and tail number:
- | | | |
|------|--------|--|
| 2436 | 4 Nov | Br 2 engine change. Internal oil leakage. removed and replaced Br 2 engine and replaced seals. |
| 2439 | 7 Nov | Fed swp due to engine valve leak - removed and replaced valve. |
| 1015 | 13 Nov | Fuel leak at tank. Injered coolant. |
| 2440 | 14 Nov | Special inspection of wheel and brakes after due to emergency landing. |
| 2449 | 14 Nov | Fuel leak at tank. Repair accomplished by Depot Airframe Team. |
| 1023 | 20 Nov | Cracked spar left wing station - 13.25. Depot engineer patch plate installed. |
| 2468 | 28 Nov | Fuel leak at tank. Injered coolant. |
| 2460 | 22 Nov | Fuel leak Br 2 engine. Injered coolant. |
| 2454 | 25 Nov | Fuel leak Br 4 engine. Injered coolant. |
5. The 8 material into take offs; of cause and aircraft tail number:
- | | | |
|------|--------|---|
| 2430 | 1 Nov | No ignition Br 1 engine. Removed and replaced main ignition unit. |
| 2430 | 5 Nov | Br 4 engine surging at pre T/O check. Removed and replaced amplifier temperature control. |
| 1122 | 5 Nov | broken wire on filler H-92 connector. Reaired wire. |
| 1011 | 7 Nov | engine mount bolt stripped. Replaced bolt and nutting. |
| 2479 | 12 Nov | Br 1 engine hydraulic pressure life on. Reaired and replaced pressure switch. |
| 2078 | 15 Nov | Left hand elevator Br 10 actuator leaking. Removed and replaced Br 10 actuator. |
| 1011 | 21 Nov | Fed swp-leak at pod to aircraft disconnect drain. |
| 2078 | 22 Nov | Fed swp-leak at pod to aircraft disconnect drain. |
6. The 4 air aborts by cause and aircraft tail number:
- | | | |
|------|--------|---|
| 2440 | 12 Nov | Lost utility hydraulic system. Replaced line on brake shutoff valve. |
| 2436 | 19 Nov | Lost cabin pressure. Replaced coupling on cool duct. |
| 2446 | 22 Nov | No cabin pressure. Removed and replaced cabin pressure regulator. |
| 1010 | 29 Nov | 38 + 250 power pack flux. Smoke in cockpit. Removed and replaced AC generator and drive assembly. |

438 Bomb Wing - November 1948

TR-48 SCHEDULING EFFECTIVENESS AND ACCOMPLISHMENTS

1. The information that follows is an extract from the 1-SAC-102 Report and reflects the TR-48 activity for November and the preceding 6 months:

	MAY	JUN	JUL	AUG	SEP	OCT	NOV
Sorties Scheduled	92	71	83	65	71	85	75
Sorties Cancelled	19	12	12	13	18	28	32
Sorties Added	2	4	3	2	5	5	4
Sorties Airborne	75	63	72	54	58	62	47
Sorties Early/Late	22	16	14	15	15	24	12
Sorties On Time	53	47	58	39	43	38	35
Air Aborts	6	0	1	0	0	0	0
Hours Flown	185	155	210	170	138	199	128
Average Sortie Length	2.5	2.5	2.9	3.1	2.4	3.2	1.7

2. The schedule deviation causes for November were:

	ADD	MIN	CANX	TOTAL
FAA	1	2	1	1
Weather	3	1	2	2
Operations	10	27	57	4
Material	3	3	3	4
Supply	1	1	1	1
SAC				

3. The material and supply deviations for November by system:

	LATE	CANX	TOTAL
Auto Pilot	1	1	1
Fuel System	3	6*	9
Air Frame	2	17	19
Power Plant	4	1	5
Hydraulic Pwr Supply	1	1	1
Landing Gear	2	2	2
Flight Control	1	2	3
Total	16	36	40

* Supply -- 3 CANX

4. 3d Tank Wing - November 1968

4. The 3d Material cancellations for November; by cause and amount: tail number:

668 1 Nov 1st sortie - Nr 1 engine hot start. Removed and replaced engine.
 668 4 Nov 2nd sortie - A/C tank indicator out of tolerance. Repaired 3/4 connector at bulkhead 3.
 668 5 Nov 1st sortie - A/C tank indicator out of tolerance. Removed and replaced w/c tank w/c.
 668 8 Nov 1st sortie - Fuel leak left forward w/c.
 669 12 Nov 2nd sortie - Auto trim drive down 1/2 follow. Adjusted auto trim stick.
 661 13 Nov 1st & 2nd sortie - Base strut cylinder cracked. Removed and replaced w/c strut.
 661 15 Nov 2nd sortie - Base bumper cushion live case on and would not reset. Replaced cushion wire behind bumper barrel.
 670 18 Nov 1st, 2nd & 3rd sortie - (Supply) Fuel reservoir manifold leaking - 100%.
 661 19 Nov 1st sortie - Fuel leak - left tank w/c wiring.
 668 19 Nov 1st, 2nd & 3rd sortie - Fuel leak Nr 2 piston. Tank entry required.
 661 20 Nov 1st sortie - Nr 3 engine hydraulic leak. Removed and replaced Nr 3 flow shutoff valve.
 661 20 Nov 2nd sortie - Nr 12 hydraulic ram leakage. Removed and replaced by 11. A/C tank connector.
 668 20 Nov 1st, 2nd & 3rd sortie - Fuel leak Nr 2 piston. Tank entry required.
 668 21 Nov 1st, 2nd sortie - Fuel leak Nr 3 piston. Tank entry required.
 670 21 Nov 1st, 2nd & 3rd sortie - Nylon struts fittings leaking. Tank entry required.
 670 27 Nov 1st & 2nd sortie - Nylon attach fitting leaking. Tank entry required.
 668 27 Nov 1st sortie - Fuel leak Nr 2 piston. Tank entry required.
 670 28 Nov 1st sortie - 1st station energy live on. Repaired wire on connector plug.
 668 29 Nov 2nd sortie - All fuel tank gage fluctuates. Broken wire inside cable.

5. The 10 Material late take offs by cause and tail number:

670 5 Nov 1st sortie - No rotation Nr 4 engine. Starter shaft sheared.
 670 12 Nov 1st sortie - Nr 3 left hand elevator actuator leaking. Removed Nr 3 actuator.
 661 18 Nov 2nd & 3rd sortie - CG out of tolerance. Calibrated CG system.
 670 25 Nov 2nd & 3rd sortie - Insufficient maintenance time after 1st sortie cancelled.
 661 25 Nov 2nd sortie - Started connector reservoir tank indicator. Repaired connector.
 670 26 Nov 2nd sortie - A/C tank fluctuates. Repaired coaxial connector at bulkhead probe 3A.
 668 26 Nov 2nd sortie - Nr 2 engine oil leak. Replaced garrick seal.
 668 29 Nov 1st sortie - Fuel pump leaking on Nr 1 engine. Removed and replaced fuel pump.
 670 29 Nov 1st sortie - No rotation Nr 1 engine. Starter shaft sheared.

438 Bomb Wing - November 1968

AIRCRAFT UTILIZATION

The following reflects the bomber aircraft, and maintenance team utilization for the month of November 1968:

TEAM #2	ACFT	SECTD	TOTAL CHX	MAY CHX	MAIE	AMN	TOTAL MAIE	MAY LTO	AIR ASST	DATE ON ASBRT	HSR PLACED
	010	2	0	0	0	2	2	0	0	25	16.1
	011	4	0	0	0	4	4	0	0	13	31.4
	021	3	1	1	0	2	2	0	0	0	6.3
	436	5	2	1	3	6	6	1	1	5	31.2
	438	3	1	0	0	2	2	0	0	26	13.8
	450	0	0	0	0	0	0	0	0	36	0
Total		17	4	2	3	16	2	1	1	69	97.8
TEAM #3	014	6	1	0	0	5	5	0	0	13	4.6
	015	4	2	1	0	2	2	0	0	19	15.6
	429	4	0	0	0	4	4	1	0	0	23.8
	430	2	0	0	1	3	2	2	0	18	14.7
	433	0	0	0	0	0	0	0	0	37	0
	435	2	0	0	0	2	2	0	0	25	14.6
	078	7	0	0	1	8	3	2	0	0	45.0
Total		25	3	1	2	24	6	4	0	165	163.2
TEAM #4	C18	4	2	0	2	4	4	1	0	0	16.0
	441	7	0	0	0	7	7	0	0	4	53.0
	442	4	0	0	0	4	4	0	0	12	29.2
	457	3	1	0	0	2	2	0	0	19	15.7
	463	0	0	0	0	0	0	0	0	90	0
	440	2	1	1	1	3	3	1	1	10	10.2
Total		21	4	1	3	20	1	1	1	75	124.8
TEAM #5	431	7	1	0	1	7	7	0	0	6	50.4
	445	5	0	0	0	5	5	0	0	25	8.3
	446	1	0	0	0	1	1	0	0	12	33.8
	121	1	0	0	0	1	1	0	0	23	8.0
	456	4	1	0	1	4	4	0	0	10	32.4
	444	2	0	0	1	3	3	0	0	18	21.0
Total		20	2	0	3	21	0	0	1	94	153.9

434 South Wing - News 1960

TEAM #	ADPT	SEMI	TOTAL	MAJ	MAJ	ADM	ADM	TOTAL	MAJ	MAJ	ADM	ADM	TOTAL	MAJ	MAJ	ADM	ADM	TOTAL
439	6	0	1	1	0	1	0	1	1	0	1	0	1	1	0	1	0	1
438	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
437	8	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
436	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
435	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
434	3	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
433	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
06A	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	30	2	2	2	3	3	3	11	2	2	0	0	8	0	0	0	0	14

MAINTENANCE TEAM UTILIZATION

TEAM #	ADPT	SEMI	TOTAL	MAJ	MAJ	ADM	ADM	TOTAL	MAJ	MAJ	ADM	ADM	TOTAL	MAJ	MAJ	ADM	ADM	TOTAL
439	6	0	1	1	0	1	0	1	1	0	1	0	1	1	0	1	0	1
438	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
437	8	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
436	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
435	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
434	3	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
433	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
06A	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	30	2	2	2	3	3	3	11	2	2	0	0	8	0	0	0	0	14

43d Bomb Wing - November 1948

MO-135 SCHEDULED EFFICIENCY AND ACCOMPLISHMENTS

1. The information that follows is an extract from the 1-SAC-182 Report and reflects the MO-135 activity for November and the preceding 6 months:

	MAY	JUN	JUL	AUG	SEP	OCT	NOV
Sorties Scheduled	122	94	84	101	114	99	80
Sorties Cancelled	22	16	7	21	19	19	9
Sorties Added	5	17	25	22	12	11	7
Sorties Airborne	105	95	107	95	107	91	78
Sorties Early/Late	10	10	9	17	6	8	13
Sorties On Time	95	85	93	82	101	83	65
Air Aborts	1	0	2	0	1	0	2
Hours Flown	521	399	444	429	450	447	421
Average Sortie Length	5.6	4.2	4.4	4.3	4.2	4.9	5.4

2. The schedule deviation causes for November were:

	ALL	LATE	CAUSE	TOTAL
FAA	5			5
Weather	1			1
SAC	5	4	8	17
Operations	1			1
Material	2			2
NAF	2			2
Total	7	13	9	29

3. Material deviations for November by system:

Power Plant 2 late take offs

4. The 2 material late take offs by cause and tail number:


0345 19 Nov Nr 3 engine fuel leak. Replaced seal on fuel pump shaft.
 0336 26 Nov Nr 4 engine did not show rotation. Removed and replaced tach generator.

5. The 2 air aborts by cause and tail number:

0346 18 Nov Nr 1 engine smoking. Removed and replaced engine.
 1470 20 Nov Lost all hydraulic quantity. Replaced cracked union on pressure filter.

434 East Wing - Bureau

1-2-1960




FOD RATE

ITEM	DEC	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV
NEW MALFUNCTION	181	162	128	113	170	226	171	169	74	129	108	87
1000 MORN	0	24	8	9	2	1	8	0	8	5	6	0
111 FUNST	8	18	19	21	5	9	16	10	10	3	5	5
OTHER	94	109	103	66	32	76	84	80	41	31	53	76
(FOD) 116 CUT	0	0	0	0	0	0	8	1	1	0	0	0
(FOD) 540 PUNCTURED	283	313	258	209	209	312	287	260	134	176	172	166
TOTAL	94	109	103	66	32	76	92	81	42	31	53	76
TOTAL FOD	180	197	170	180	205	216	202	202	213	179	207	178
SORTIES FLOKN	.52	.55	.61	.56	.61	.65	.46	.57	.60	.57	.66	.59
FOD RATE	SOURCE: MOC RPT #5											

The number of tire changes decreased during the month of November. An increase was noted in FOD while there was a decrease in the number of tires "worn". The partial cause for the higher rate of .59 is due to a decrease in the number of sorties flown.

43d Bomb Wing - November 1968 -


1-27 ENGINE SHUTDOWNS



The 1 shutdown was the Nr 1 on A/cft 0346. The shutdown occurred on 18 November and was due to fluctuating oil pressure. The engine was removed, replaced and subsequently repaired by replacing 4g carbon seal and the front bearing support.

434 Bomb Wing - November 19


1-79 ENGINE SHUTDOWNS



The 1 shutdown during November was the Nr 3 on aircraft 2444. The shutdown occurred 4 November due to a low oil light. This was preceded by decompling the generator due to a generator light. Engine was removed and replaced and subsequently shipped for Nr 2 bearing failure.

43d Bomb Wing - November 1968

KC-135 NORM RATES



SOURCE: Aerospace Vehicle Status Report FCN 20006A

43d Bomb Wing - November 1968

EC-122 NORM

1. The NORM rates exceeded the DOD standards for the first time since April. An increase in unscheduled maintenance and phased inspection contributed to the overall increased rate.

2. The high NORM systems were:

Landing Gear	383	Radar Nav	178
Power Plant	276	Flight Control	126
Fuel	200	UHF Communications	114
Instruments	191	Electrical	167


3. The high NORM aircraft were:

1471 - Primarily on instrument system, fuel system and landing gear.
 1467 - Primarily on electrical system.
 0346 - Primarily on power plant system.
 1470 - No one particular system. The electrical, power plant, flight control, UHF, instruments, landing gear and airconditioning systems were involved.
 0343 - Primarily landing gear.
 0345 - Primarily radar nav.
 0344 - Primarily instruments.

4. Requirements to accomplish phased inspections prior to forward base deploy, contributed to increased phased inspection rates and overall NORM rates.

434 Bomb Wing - November 1968

II-PS NORM RATE



SOURCE: Aerospace Vehicle Status Report PON 22006A

438 Bomb Wing - November 1968

B-58 MCM

1. The B-58 MCM rates are above the DOP Maximum for the second consecutive month and for 5 of the 8 plotted months. The 27.6 percent represents 6953 hours and based on 720 hours for the month, equates to 9.7 aircraft per day, every day of the month.
2. Overall, 35 aircraft reflected MCM time during November. The time ramped upwards to more than 400 hours for some aircraft. There were 8 aircraft contributing to approximately 45 percent of the total MCM time. These acft and systems were:
 - 1015 - Primarily the airframe system - fuel leaks
 - 1421 - Airframe and electrical system
 - 2439 - Primarily the fuel system - CG problems
 - 2440 - Auto pilot and radar nav
 - 2458 - Primarily the airframe system - fuel leaks
 - 2460 - Fuel, bomb-nav, ECM and radar nav systems
 - 2864 - Airframe and bomb-nav systems
 - 2878 - Hydraulic, bomb-nav, flight control, UHF communications, power plant and ECM systems
3. Unscheduled maintenance is the area where emphasis must be placed to bring MCM rates within standards. Phased inspection rates are not a problem at this time.

434 Bomb Wing - November 1968


E/A/TB-52 CANNIBALIZATIONS

The following is a list of items cannibalized showing the number of items and the reason for cannibalization:

P/N	MOON	REASON	TIMES CANNIB	
			CURRENT	PREVIOUS
661F-396-4794	Amp Computer Assy, Y&M	To Prevent MRC	1	0
1660-776-4247	Control Valve	To Prevent MRS	1	0
1660-776-4247	Control Valve	Maintenance Convenience	1	0
668F-473-7966	Indicator, BIT	Maintenance Convenience	1	0
1660-776-0291	Control Valve	Maintenance Convenience	1	0
1660-799-8470	Regulator	To Prevent MRS	1	0
668J-886-4183	Transmitter	To Prevent MRS	1	0
1660-691-6946	Support	To Prevent MRS	1	0
6680-886-4185	Detector	To Prevent MRC	1	0
7899-792-4258	Rotary Joint	Maintenance Convenience	1	0

434 Bomb Wing - November 1968

F/FU-58 CAMPAIGNIZATIONS



SOURCE: RGS: 1-SAC-082
AF Form 991

433 Bomb Wing - November 1964


KC-125 MAINTENANCE

The following is a list of items maintained showing the number of items and the reason for maintenance:

P/N	QTY	REASON	TIMES MAINT	
			CURRENT	PREVIOUS
6610-824-8618	2	To Prevent NORS --	2	0
1610-765-9187	1	To Prevent NORS	1	0
2995-956-0581PH	1	To Prevent NORS	1	0
9841-832-8543	1	To Prevent NORS	1	0

43d Bomb Wing - November 1968

KG-125 CAPITALIZATIONS



SOURCE: RGS; 1-64C-182
AF Form 991

43d Bomb Wing - November 1966

REPEAT WHITE-UFS E-48

1. There were 131 sorties flown with repeats occurring on 68 sorties. They range from 1 to 5 per sortie as follows:

- 1 Repeat on 99
- 2 Repeats on 24
- 3 Repeats on 2
- 4 Repeats on 1
- 5 Repeats on 2

2. The reliability code distribution on the repeats was 65 code 2, 41 code 3 and 1 code 5. The distribution of the repeats by system are as follows:

SYSTEM	CODE 2	CODE 3	SYSTEM	CODE 2	CODE 3	SYSTEM	CODE 2	CODE 3
Engine	0	0	Doppler	2	15	Auto Pilot	3	1
A/C Press	2	1	E/W	28	1	IFF Radio	4	4
A/Refuel	2	0	ECM Rec	0	1	Oxygen	1	0
Instrument	2	0	R.V. Beacon	0	2	Radar Alt	2	2
STEY Comp	1	0	Elec Pwr Sup	0	2	Nav	0	0
Compass	3	0	Fuel (Other)	6	0	ECM Trans	1	2

3. There were 11 repeat code 3 that were code 2 on the previous sortie. These repeats were on the following systems:

SYSTEM	REPEATS	SYSTEM	REPEATS
Auto Pilot	1	ECM Rec	1
Radar Alt	1	Nav	1
Doppler	3	IFF	1
E/Nav	2	Electric	1

4. There were 30 repeat code 3 that were code 3 on the previous sortie. These repeats are on the following systems:

SYSTEM	REPEATS	SYSTEM	REPEATS
A/C Press	1	IFF Radio	3
Radar Alt	1	Doppler	12
Elec Pwr Supply	1	Nav	8
R.V. Beacon	2	ECM Trans	2

5. The repeats followed the normal system pattern with 78.5% going to the electronics area. This is the case in both code 2 and 3 repeats.

434 Bomb Wing - November 19

6. The following aircraft had more than one repeat write-up on a single system during the month of November. The aircraft tail number and repeat system are listed below:

ACFT #	DATE	SYSTEM	CODE	REPEAT #
2018	21 Nov	UHF Radio	3	1
	26 Nov		3	2
	29 Nov		3	3
2078	4 Nov	Doppler	3	3
	6 Nov		3	4
1122	14 Nov	UHF Radio	3	3
	1 Nov		3	3
2430	5 Nov	Doppler	3	3
	18 Nov		3	4
2459	20 Nov	Bomb/Nav	2	1
2471	19 Nov	R.V. Beacon	2	2
	25 Nov		3	1
	25 Nov		3	2
2456	27 Nov	Flight Control	2	1
	4 Nov		2	2
	8 Nov		3	1
	13 Nov		3	2
2458	15 Nov	Doppler	3	2
	6 Nov		3	4
	8 Nov		3	2
	25 Nov		2	3
2458	27 Nov	Doppler	2	1
	25 Nov		2	2
	27 Nov		2	2
2458	27 Nov	Bomb/Nav	2	1
	29 Nov		2	2

43d Bomb Wing - November 1960

WORK CENTER	MANHOUR UTILIZATION										TOTAL	
	SHOP	P-58	POD	KC-135	BF/TR	AGE	SUPPLY	OTHER			TOTAL	
23110 Machine	848	61	44	14	8	128	21				108	
120 Welding	112	4	131			224	2				573	
130 Struct Rep	187	40	74			132	28				422	
150 Survival Equip	6					4					27	
155 Fabric	8		1				53				66	
160 Corr Cont	40		126		51	34					254	
170 NDI	6		4								10	
210 Reciv Engine	5										5	
220 Prop Shop				1							1	
230 Jet Engine	233		674		43	54					924	
310 Aero Rep	175		44			62					281	
320 Fuel System	1261		17								1278	
330 Electric Shop	144		53		61	205	1				464	
340 FHEB	308		773		28	27					1136	
350 Instrument	1217		40		132	18					1407	
360 M/A	1763		477		69	147					2456	
370 Wheel/Tire	43		112				121.5				176.5	
380 IFR	68		130								198	
390 Egress	1676		5								1681	
410 AGE Repair			6			2634					2640	
420 Insp & Serv						2536					2536	
430 P.U./Delivery						1262					1262	
TOTAL PMS	18793	435	8315	803	2328	294	294	294	294	294	41129	
25110 P-58 CO & L	2397		860	28		2					3287	
120 Weapon Rel	6		2895	2		303					3206	
210 Nuclear Wp	5		1475			7					1487	
220 EOD Conv	1			8		36					45	
250 Re-Entry			18			228					246	
TOTAL PMS	2469	5243	38			626					10928	

43d Bomb Wing - November 1960

WORK CENTER	MANHOURLY UTILIZATION				AGE	SUPPL	OWNER	TOTAL
	F-58	POU	AG-135	BF7R				
22101 SHOP	1417	86					1503	
102 TB Maint Team	1298	18			7		1316	
103 Team #2	2297	43					2340	
104 Team #3	1260	34					1294	
105 Team #4	1281	8					1289	
106 Team #5	1122	14			2		1136	
107 Team #6	1227	32			3		1260	
108 Tanker Team #8	24						24	
111 Tanker Team #11	1698						1698	
185 Non Pwr ACE	1473						1473	
188 Phase Team	1959				1168		3127	
310 Fixed Wg A/G	216						216	
311 Helicopter	1798						1798	
320 Transient	1304						1304	
	311				3		314	
Total	15853	230	4174	4779	1182	27	25662	
24110 Radio	1156	14	262	152	204	68	1752	
120 Radar	685	6	432	103	165	36	1227	
125 Doppler	30		427	15			442	
131 EM Shop	1166	7		121	25	1	1319	
210 Fire Control	1378	6	4	87	54		1523	
310 Bomb Nav	4013			12	17	304	4046	
320 Flt Control	1372	6			3	103	1481	
31 KC Antropilot	4		332	44	56	54	450	
400 Photo	33				1		34	
500 PWBL								
TOTAL	10162	39	1457	325	654	743	12379	
TOTAL WING	47772	5952	13484	5868	11760	3978	74922	

SOURCE: Report 3-1. The figures portrayed indicate the manhours documented on AFTO 3491's. There were 19 working days during this month.

43 H10 T

43D BOMB KING
LITTLE ROCK AFB ARK 72076
DECEMBER 1968

MAINTENANCE SUMMARY

101484

MAINTENANCE SUMMARY

FOREWORD

43 Bomb Wing

1. This Maintenance Summary is developed and published each month by the Analytic Division of the Deputy Commander for Maintenance in accordance with Volume VI, SACM 66-12.
2. This summary is designed for use of local maintenance managers and the contents will be based on the desires of local management. Maintenance supervisors are invited to contact the Analytic Division on items to be included in this summary and/or any other special analyses. Data is available in the following areas:
 1. Maintenance Item Collection System. This covers such areas as component failures, repair rates, material variations, type maintenance performed, action taken codes and all areas of the MEX System.
 2. Aircraft Loading Status Reporting System. This covers such areas as MORG rates, MOW rates, OR rates, time loading MORG, aircraft loading MORG and MRM, etc.
 3. Air Vehicle Performance Reporting System. This covers scheduling effectiveness, aircraft utilization, airframe effectiveness, launch effectiveness, USAF information, repeat write-ups, etc.
3. The above listing reflects the broad areas of data available. If an analysis or study on the above or any subject relating to the maintenance effort is desired, contact DCM Analytic.

James D. Hickey
 JAMES D. HICKEY, USAF
 Deputy Commander, Maintenance

43d Bomb Wing -- December 1968

DISTRIBUTION

305 Bomb Wg			
8251N	2		
43C	2		
43DM	1		
43DQ	1		
43DR	1		
43DHA	1		
43DHT	5		
43DMAQAE	1		
43DMC	1		
43DMS	1		
43DMG	1		
43DMG	5		
43AMS	5		
27MWC	5		
3X1H	1		
3X1B-AP	1		
31C FTD	1		
308DMA	1		
GE (196)	1		
RDRE	1		
43D HISTORIAN	4		
43DCCITS	4		
	1		

43d Remo Wing - December 1968

TABLE OF CONTENTS

Foreword	3
SAC Form 481 - OI Manhours Per Service	4
SAC Form 473 - Maintenance Production on Aircraft	7
SAC Form 509/5/9a - Base Staff Satisfaction	12
B-58 Accomplishments	14
TB-58 Accomplishments	17
B-58 Tire PCD	18
Number Aircraft & Maintenance Team Utilization	20
EC-135 Accomplishments	22
EC-135 MORM	24
B-58 MORM	26
B/TB Quantification	28
EC-135 Quantification	30
Repeat Write-Ups - B-58	30
Manhour Utilization	32

01 MANHOURS PER SORTIE/HOUR		ORGANIZATION	REPORTING PERIOD
		434 Bomb Wing	December
		NARRATIVE (Continue)	
I. 01 MANHOURS PER SORTIE			
BOMBER	B/7B-58		
	WING	OCT	NOV
	COMB	287.3	301.4
	ACAS	88.6	87.1
	FAW	59.4	57.2
	WAS	107.7	107.4
	AUS	79.4	82.2
			16.4
TANKER	KC-135		
	WING	190.8	179.3
	COMB	74.2	53.6
	ACAS	24.2	18.7
	FAW	26.0	10.6
II. 01 MANHOURS PER FLYING HOUR			
BOMBER	B/7B-58		
	WING	54.1	56.3
	COMB	16.7	16.0
	ACAS	11.2	10.3
	FAW	20.7	21.1
	WAS	5.5	9.0
			3.4
TANKER	KC-135		
	WING	38.7	32.9
	COMB	15.1	9.8
	ACAS	4.2	3.4
	FAW	19.5	19.5
			16.5
NARRATIVE			
B/7B-58: The overall cost per sortie decreased considerably during December as compared with November. Cost per flying hour also decreased while the total number of flying hours was the same as for November.			
NOTE: Manhours expended on supply and other suffixes non-identifiable to aircraft were not used in computation, although they were in support and distributed among:			
		B/F Transient	61.3
		A/E	99.8
		Supply	31.27
		All Others	62.33

MAINTENANCE PRODUCTION ON AIRCRAFT				ORGANIZATION	REPORTING
SORTIE PRODUCTION		PREVIOUS	LAST	434 Bomb Wing	December 1948
TYPE AIRCRAFT	EC-119	QOE	80V	REMARKS	
AIRCRAFT POSSESSED		16.7	13.8	Sortie flown represent all sorties reported in the SAC-182 Report. Of the 80 sorties shown, 17 were launched away from the home station, but shown as 12 deploy sorties that are reported by the forward base.	
AIRCRAFT AVAILABLE		8.9	9.3		
SORTIES FLOWN		91	78		
SORTIES PER AVAIL AIRCRAFT		10.2	8.4		
HOURS FLOWN		447	424		
HOURS PER AVAIL AIRCRAFT		50.2	45.6		
RECOVERY TIME (Average) PER MONTH		2.3	2.3		
TIME TO OR (Average)					
TYPE AIRCRAFT					
AIRCRAFT POSSESSED					
AIRCRAFT AVAILABLE					
SORTIES FLOWN					
SORTIES PER AVAIL AIRCRAFT					
HOURS FLOWN					
HOURS PER AVAIL AIRCRAFT					
RECOVERY TIME (Average)					
TIME TO OR (Average)					
TYPE AIRCRAFT					
AIRCRAFT POSSESSED					
AIRCRAFT AVAILABLE					
SORTIES FLOWN					
SORTIES PER AVAIL AIRCRAFT					
HOURS FLOWN					
HOURS PER AVAIL AIRCRAFT					
RECOVERY TIME (Average)					
TIME TO OR (Average)					

MAINTENANCE PRODUCTION ON AIRCRAFT				ORGANIZATION	REPORTING
SORTIE PRODUCTION		PREVIOUS	LAST	433 Base Wing	December 1968
TYPE AIRCRAFT	5-58	OUT	IN	REMARKS	
AIRCRAFT POSSESSED		34.0	34.9	Overall sortie production was effected by 27 specialists: 11 Weather, 9 Material, 2 SAC and 1 Ops. The specialists were offset by 20 additions for a net loss of 13 sorties. Of the 13 sorties flown 7 were launched away from the base station.	
AIRCRAFT AVAILABLE		17.8	18.1	Turn Around days measure the average time it took to fly and maintain 1 sortie based on normal flying and maintenance days.	
SORTIES FLOWN		145	131		
SORTIES PER AVAIL AIRCRAFT		8.1	7.2		
HOURS FLOWN		873	842		
HOURS PER AVAIL AIRCRAFT		25.2	24.5		
RECOVERY TIME (Average) Turn Around Days		2.8	2.6		
TIME TO OR (Average)					
TYPE AIRCRAFT	T3-58				
AIRCRAFT POSSESSED		2.7	2.6		
AIRCRAFT AVAILABLE		2.7	2.6		
SORTIES FLOWN		62	47		
SORTIES PER AVAIL AIRCRAFT		23.0	18.1		
HOURS FLOWN		199	128		
HOURS PER AVAIL AIRCRAFT		72.7	49.2		
RECOVERY TIME (Average) Turn Around Days		1.0	1.0		
TIME TO OR (Average)					

WORK CENTER	BASE SELF SUFFICIENCY													SQUADRON			DATE																								
	BING 432 Bomb Wing													December 1948		December 1948																									
	SELF SUFFICIENCY EVALUATION CODES													TOTAL NRTS	TOTAL PROCESSED	SELF SUFFICIENCY RATE																									
REPAIR CODES													PREVIOUS MONTH			LAST MONTH	CURRENT MONTH																								
NRTS CODES													TOTAL		RATE																										
A	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0
REMARKS																																									

The overall wing repair rate showed a sharp increase during the month of December; 96.7 in November, 96.6 in December. The NRTS code 4, "Lack of Parts," continues to be the major problem area, causing 88.2 percent of the NRTS actions.

SHOP ACTIONS TAKEN																		
WING 49d Bomb Wing																		
Percentage 1968																		
WORK CENTER	ACTION TAKEN CODES												REMARKS					
	B	C	D	E	J	M	N	P	Q	R	S	T	U	V	W	X	Y	Z
1. ENG	10.59				46	14	9							346		136	4	26
2. AWC	162	145			447									2	114	11	48	
3. FLT SIMULATOR																		
4. MMG																		
5. WING TOTAL	174	290			493	14	9							372	155	65	74	
6. ENG																		
7. AWC																		
8. FLT SIMULATOR																		
9. MMG																		
10. WING TOTAL	4.5	4.8			5.0	18.8	27.5											
11. ENG	4.7				17.2	29.0	27.4											
12. AWC	10.7	12.0			14.1	21.6	22.4											
13. FLT SIMULATOR																		
14. MMG	0.0	0.0			0.0	15.0	29.7											
15. WING TOTAL	15.7	16.8			17.2	29.0	27.4											
16. ENG	10.7	12.0			14.1	21.6	22.4											
17. AWC	4.0	4.8			5.0	18.8	27.5											
18. FLT SIMULATOR																		
19. MMG																		
20. WING TOTAL	15.7	16.8			17.2	29.0	27.4											

Code B and I percentages sometimes fluctuate. No problem areas were noted.

WORK CENTER		SHOP ACTIONS TAKEN												REMARKS											
		B	C	D	E	F	J	M	N	P	Q	R	S	T	U	V	W	X	Y	Z					
1	2410 Radio	19	15																						
2	2413 Radar	14	29																						
3	2415 Decoder	2	2																						
4	2413 SW Shop	27	27																						
5	2410 FIRE CONT.																								
6	2410 FIRE CONT.	8	8																						
7	2413 FIRE CONT.	2	4																						
8	2413 Autopilot	1	1																						
9	2410 Radio	6	1																						
10	2410 PMS																								
11																									
12																									
13																									
14																									
15																									
16	Shop Total	107	118																						
17																									
18																									

WORK CENTER	CODE B.1		CODE B.2		CODE B.3		REMARKS
	PREVIOUS MONTH	LAST MONTH	CURRENT MONTH	PREVIOUS MONTH	LAST MONTH	CURRENT MONTH	
1 2410 Radio	9.4	10.0	11.2	0.0	6.6	0.0	The code 1 and 2 percentage continued to fluctuate during the month of December. No problem areas were noted.
2 2413 Radar	10.7	2.8	13.1	6.1	6.6	13.1	
3 2415 Decoder	2.2	8.7	8.7	17.7	34.8	52.2	
4 2413 SW Shop	12.2	5.4	24.9	21.8	27.0	21.7	
5 2410 FIRE CONT.	0.0	0.0	0.0	16.4	13.8	14.3	
6 2413 Autopilot	14.0	17.8	17.3	25.1	21.2	24.4	
7 2410 Radio	1.0	2.0	2.4	61.4	70.2	77.4	
8 2413 Autopilot	3.2	0.0	7.7	48.4	28.3	54.2	
9 2410 PMS	0.0	4.4	28.6	39.3	17.4	19.0	
10 2410 PMS	0.0	0.0	0.0	57.1	0.0	50.0	
11							
12							
13							
14							
15							
16 Shop Total	107	118	141	216	220	255	
17							
18							

WORK CENTER	BASE SELF SUFFICIENCY													SQUADRON	DATE			
	SELF SUFFICIENCY EVALUATION CODES											TOTAL REPAIR	HRTS CODES		TOTAL HRTS	TOTAL PROCESSED	December 1968	
	REPAIR CODES			HRTS CODES					SELF SUFFICIENCY RATE									
A	F	G	K	L	Z	R	3	4	5	6	7		PREVIOUS MONTH	LAST MONTH	CURRENT MONTH			
2111	10											150						
2112	10											164						
2113	10											240						
2114	10											224						
2115	10											270						
2116	10											66						
2117	10											6						
2118	10											8						
2119	10											20						
2120	10											119						
2121	10											2						
2122	10											22						
2123	10											2169						
2124	10											11						
2125	10											1						
2126	10											1						
2127	10											1						
2128	10											128						
2129	10											2						
2130	10											2						
2131	10											2						
2132	10											2						
2133	10											2						
2134	10											2						
2135	10											2						
2136	10											2						
2137	10											2						
2138	10											2						
2139	10											2						
2140	10											2						
2141	10											2						
2142	10											2						
2143	10											2						
2144	10											2						
2145	10											2						
2146	10											2						
2147	10											2						
2148	10											2						
2149	10											2						
2150	10											2						
2151	10											2						
2152	10											2						
2153	10											2						
2154	10											2						
2155	10											2						
2156	10											2						
2157	10											2						
2158	10											2						
2159	10											2						
2160	10											2						
2161	10											2						
2162	10											2						
2163	10											2						
2164	10											2						
2165	10											2						
2166	10											2						
2167	10											2						
2168	10											2						
2169	10											2						
2170	10											2						
2171	10											2						
2172	10											2						
2173	10											2						
2174	10											2						
2175	10											2						
2176	10											2						
2177	10											2						
2178	10											2						
2179	10											2						
2180	10											2						

REMARKS: The overall squadron repair rate increased during December. Aero repair shop failed to achieve the desired 95 percent goal due to the low number of items processed. Work centers with no items processed are not included in these calculations.

434 Bomb Wing - December 1968

1-58 SCHEDULED EFFICIENCY AND ACCOMPLISHMENTS

1. The information that follows is extracted from the 1-58-583 Report and reflects the 1-58 activity for December and the preceding 6 months:

	MIN	MAX	AVG	DEL	DEL	LOI	DEL
Schedule Scheduled	143	150	148	178	10%	177	177
Schedule Cancelled	10	10	14	11	31	31	31
Schedule Added	7	9	15	6	31	15	10
Schedule Airborne	139	149	143	143	14%	141	144
Schedule Early/Late	15	10	11	15	12	19	19
Schedule On Time	104	139	148	146	13%	132	115
Air Alerts	2	6	6	2	3	2	2
Hours Flown	78	85	100	708	8%	82	82
Average Schedule Length	9.1	5.1	5.1	5.9	6.2	6.4	6.1

2. The schedule deviation counts for December were:

	ARR	LTO	CRK	AVIAL
Weather	0	2	11	21
CRK	3	2	1	2
Material	1	12	9	22
Receiver/anker	2	2	2	2
SWR				
Total	10	19	23	52

3. Material deviations for December by system:

	LTC	DATA	AIR	AVIAL	TOTAL
Air Frame	1	2			3
Auto Pilot	1				1
Instrument	3	1			4
Power Plant	2	2			4
Elect Fuel Supply	2	2	1		5
Fuel System	1				1
Bomb Bay	1	1	1		3
Hydraulic	1	2			3
Landing Gear	1				1
WIP	12	9	2		23
Total	12	9	2		23

43d Post Wlog - December 1948

4. The 9 Materiel cancellations by cause & all number:
- | | | |
|------|--------|---|
| 1019 | 4 Dec | Fuel leak - right wheel well fairing |
| 1021 | 5 Dec | Nr 3 generator coupling shaft sheared. Removed and replaced coupling shaft. |
| 1030 | 6 Dec | Nr 4 engine oil pressure high. Low KFI on take off roll. Removed and replaced Nr 4 engine |
| 2439 | 10 Dec | Nr 5 brake dragging. Removed and replaced fuel inlet brake arm |
| 2435 | 13 Dec | Wass strut leaking. Replaced seals |
| 1021 | 17 Dec | Nr 1 hydraulic pressure live on. Removed and replaced pressure switch and pump |
| 2458 | 17 Dec | Fuel quantity flux. Started cable at ACA probe |
| 2444 | 30 Dec | Hole in Rt walkway panel. Patched hole |
| 2449 | 30 Dec | On out of tolerance. Removed and replaced callibrator |
5. The 12 Materiel late take offs by cause and aircraft tail number:
- | | | |
|------|--------|--|
| 2464 | 2 Dec | Hydraulic leak search radar antenna. Removed and replaced antenna |
| 2455 | 6 Dec | Nr 3 engine starter inoperative. Removed and replaced starter |
| 1014 | 9 Dec | Nr 1 generator decoupled at pre T/C. Engine run reset |
| 2435 | 9 Dec | No rotation Nr 3 engine. Starter shaft sheared. Removed and replaced shaft |
| 2454 | 10 Dec | On switch won't go out of auto. Adjusted switch |
| 2461 | 19 Dec | Fuel quantity flux. Fed resistor fuel control panel |
| 2444 | 19 Dec | Nr 2 engine vibration. Adjusted push-pull rod main control |
| 2352 | 20 Dec | Interphone blows fuses. Repaired wire control panel plug |
| 1019 | 20 Dec | Let station auxiliary attitude indicator bad. Removed and replaced indicator |
| 2450 | 20 Dec | Left main gear axle been sheared. Removed and replaced strut |
| 2433 | 30 Dec | Nr 3 generator went off line during engine run - recoupled |
| 2442 | 30 Dec | Signal to ACA continues after control stick stops. Removed and replaced ACA |
6. The 2 air aborts by cause and aircraft tail number:
- | | | |
|------|-------|---|
| 2445 | 2 Dec | Cannot air refuel; ready lite not on and air refueling door unopen. Removed and replaced signal amplifier |
| 2458 | 5 Dec | Clamp broken on hot air line and damaged seals in hydraulic shutoff valve. Removed and replaced valve. |

43d Bomb Wing - December 1968

TABLE 2 - SCHEDULING EFFECTIVENESS AND ACCOMPLISHMENTS

1. The information that follows is an extract from the 1-SAC-152 Report and reflects the TD-58 activity for December and the preceding 6 months:

	SEP	OCT	NOV	DEC	JAN	FEB	MAR
Services Scheduled	71	83	65	73	85	76	91
Services Cancelled	12	14	13	18	28	32	31
Services Added	4	3	3	6	5	4	4
Services Airborne	63	72	52	58	62	47	64
Services Early/Late	16	14	15	15	24	12	23
Services On Time	47	58	37	43	38	35	42
Air Aborts	0	1	0	0	0	0	0
Hours Flown	155	213	170	138	199	128	163
Average Service Length	2.2	2.6	2.6	2.4	2.3	1.7	2.5

2. The schedule deviation causes for December were:

	ADD	LTD	CAUSE	TOTAL
FAF		3		3
Weather		1	8	9
Systems	4			4
Material		18	21	41
Total	4	22	31	57

3. The Material and Supply deviations for December by system:

	LATE	CAUSE	TOTAL
Air Conditioning	1		1
Auto Pilot	0		0
Fuel System	3	4	7
Air Frame	1	2	3
Power Plant	4	2	6
Hydraulic Power Supply	1	4	5
Landing Gear	2	8	10
Flight Control	1		1
Electrical Power Supply	1		1
Instrument	1		1
Misc Utilities	2		2
UNF Comm	2		2
Interphone	1		1
Total	14		14

434 Post Wing - December 1974

4. The 23 Material cancellations for December by cause and aircraft tail number:

5670	2 Dec	2nd sortie - Lost right brake during taxi for T/O. Removed and Replaced cable
5661	4 Dec	2nd sortie - Landing Nr 3 engine quick disconnect. Removed and replaced Nr 3 self sealing quick disconnect coupling
5670	4 Dec	2nd sortie - Nr 2 engine goes into afterburner too early. Rerigged Nr 3 throttle
5661	4 Dec	4th sortie - Nr 2 Py200 leak
5661	9 Dec	1st sortie - CG out of tolerance. Calibrated CG system
5668	9 Dec	2nd sortie - EPI drove out of limits. Removed and replaced PCLA
5661	10 Dec	1st sortie - Left anti-skid sensor broken. Removed and replaced sensor
5668	11 Dec	2nd sortie - Eleven trim lite stays on. Adjusted switch on EFA
5668	12 Dec	1st sortie - Eleven trim lite stays on. Removed and replaced PCLA
5670	13 Dec	2nd sortie - B3 air to air heat exchanger leaking. Removed and replaced exchanger
5670	17 Dec	2nd sortie - Nr 3 generator flux on 1 sortie tripped off line. Removed and replaced generator
5670	17 Dec	3rd sortie - Canopy nitro leak. Removed and replaced tubing in belly of aft
5661	18 Dec	1st sortie - Balance tank takes fuel with refuel valve off. Replaced pilot line to refuel valve
5661	19 Dec	2nd sortie - Rudder oscillation. Removed and replaced control valve
5670	19 Dec	2nd sortie - Aft tank off by 2000 lbs. Replaced 5 connectors in aft tank probe
1007	23 Dec	1st sortie - Rudder position transmitter 13 degrees in error. Removed and replaced transmitter
1007	26 Dec	2nd sortie - 3 degree rudder required for taxi. Removed and replaced steering positioning transmitter
1007	30 Dec	2nd sortie - Nr 4 eng A/B leak. Removed and replaced fuel pump garter seal


43d Bomb Wing - December 1968

5. The 1B Materiel late take offs by cause and tail number:

5661	5 Dec	1st sortie - Mr 3 starter shaft shears. Removed and replaced starter shaft
5661	5 Dec	2nd sortie - 3rd station indicator ejection switch out of adjustment.
		3rd sortie - Adjusted switch
5668	5 Dec	2nd sortie - WIF weak and intermittent. Removed and replaced Mr 1 receiver
5670	6 Dec	1st sortie - No nose draw trim. Replaced P/LA fuse
5661	9 Dec	2nd sortie - Auto trim and elevator available out of limits. Elevator aileron input position transmitter
5668	11 Dec	2nd sortie - ARS-57 won't equalize. Removed and replaced M-377 receiver transmitter
5680	11 Dec	2nd sortie - Pod swap coupler leaking. Removed and replaced fuel disconnect
5670	13 Dec	1st sortie - Mr 3 engine would rotate. Adjusted electrical connection on starter
5668	13 Dec	1st sortie - Fuel quantity disagrees with fuel checks. Defuel and Refuel
5670	16 Dec	1st sortie - Mr 4 engine no RPM - scan imperative. Removed and replaced tach generator
5670	16 Dec	2nd sortie - 2nd station altimeter stuck. Removed and replaced altimeter
5668	17 Dec	2nd sortie - Interplane external receptacle plug loose. Repaired receptacle
5661	19 Dec	2nd sortie - Fuel sump bottom LR wing. Resealed fasteners
5661	23 Dec	2nd sortie - Mr 2 engine 2nd station EGT indicator reads hi. Removed and replaced indicator
5661	23 Dec	3rd sortie - 6 main gear tires out. Removed and replaced 6 main gear tires
1307	26 Dec	1st sortie - J-4 block fuses. Removed and replaced fuse
5668	26 Dec	2nd sortie - A/F tank indicates 500 lbs when empty. Calibrated fuel quantity indicator

433 Bomb Wing - December 1968

1-18 TIRE FOD



NEW MALFUNCTION	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV	DEC
020 WORN	162	128	113	170	226	171	169	74	194	108	87	177
111 BURST	24	8	9	2	1	8	0	8	3	0	0	0
OTHER	18	19	21	5	9	16	10	10	3	5	5	0
(FOD) 116 CUT	109	103	66	32	76	84	80	41	31	53	70	53
(FOD) 540 PUNCTURED	0	0	0	0	0	8	1	1	0	0	0	0
TOTAL	313	258	209	209	312	287	260	134	176	172	162	180
TOTAL FOD	109	103	66	32	76	92	81	42	31	53	70	53
SORTIES FLOWN	197	100	190	225	216	202	221	213	179	207	178	198
FOD RATE	.55	.61	.36	.14	.35	.46	.37	.20	.17	.26	.39	.27

SOURCE: MC RPT #5
 The number of tire changes increased during the month of December. A decrease was noted in FOD but there was an increase in the number of tires "worn". The reason for the lower rate is that more sorties were flown with fewer "cut" codes and no punctures.

434 Bomb King - December 1968

AIRCRAFT UTILIZATION

The following reflects the bomber aircraft and maintenance team utilization for the month of December 1968:

TEAM #	ACFT	SEHD	TOTAL CHX	MAT CHX	ADD	ADM	TOTAL	MAT LATE	MAT LTO	AIR CRT	DAVS ON ALBRE	HRS FLOOR
Total TEAM #3	013	4	0	0	4	0	4	0	0	0	0	24.3
	011	1	0	0	0	0	0	0	0	0	0	0.0
	021	9	3	2	1	7	0	0	0	0	23	0.0
	436	0	0	0	0	0	0	0	0	0	0	41.3
	438	3	0	0	0	0	0	0	0	0	30	0
	490	4	0	0	0	3	0	0	0	0	22	22.0
Total TEAM #3	25	4	2	2	1	23	3	1	0	0	85	162.3
Total TEAM #4	016	4	0	0	0	4	1	1	0	0	16	27.1
	019	0	0	0	0	0	0	0	0	0	0	0
	429	2	2	0	0	1	1	0	0	0	0	0
	431	2	1	0	0	1	2	0	0	0	0	1.0
	433	7	0	0	0	0	7	3	1	0	0	9.7
	435	9	3	1	2	9	1	1	0	0	0	27.0
Total TEAM #4	24	5	1	4	23	5	3	0	0	0	65	131.8
Total TEAM #5	018	3	0	0	0	3	0	0	0	0	16	19.7
	441	0	0	0	0	0	0	0	0	0	29	0
	442	2	0	0	0	2	2	1	0	0	23	31.1
	457	1	0	0	0	1	0	0	0	0	0	11.5
	461	7	0	0	0	7	1	1	0	0	4	47.3
	466	2	2	1	0	6	1	0	0	0	26	64.0
Total TEAM #5	21	2	1	0	19	4	3	0	0	0	98	112.6
Total	431	1	0	0	0	1	0	0	0	0	0	1.7
	445	5	0	0	0	5	1	0	0	0	11	35.9
	446	2	0	0	0	2	0	0	0	0	21	11.3
	121	8	2	0	1	7	0	0	0	0	2	44.4
	456	0	0	0	0	0	0	0	0	0	0	0
	464	3	1	1	1	0	2	1	1	0	0	15.2
Total	19	3	1	1	17	2	1	1	0	0	80	108.6

424 Bomb Wing - December 1968

TEAM #6	ADFT	SCHED	TOTAL CLK	MAT CLK	AND	ARR	TOTAL	MAT LTO	AIR ACFT	DAYS ON	MBET	HRS FLOWN
							LATE					
	437	8	1	1	1	8	0	0	0	0	0	46.8
	428	1	1	0	1	1	0	0	0	0	0	0.9
	132	0	0	0	0	0	0	0	0	29	0	0
	455	2	0	0	0	2	1	1	0	3	0	8.2
	453	4	2	0	0	2	0	0	0	0	0	8.9
	454	8	0	0	0	8	0	0	1	9	0	53.9
	064	2	0	0	0	2	1	1	0	23	0	14.2
	019	2	1	1	0	7	1	1	0	0	0	32.4
Total	33	33	5	2	2	30	3	3	1	64	0	172.3

TEAM #7	CLK	SCHED	TOTAL CLK	MAT CLK	AND	ARR	TOTAL	MAT LTO	AIR ACFT	DAYS ON	MBET	HRS FLOWN
							LATE					
	434	5	1	1	0	4	0	0	0	14	0	30.6
	434	9	1	0	0	8	0	0	0	0	0	56.8
	498	4	1	1	0	3	0	0	1	9	0	16.4
	460	0	0	0	0	0	0	0	0	31	0	0
	453	3	0	0	0	3	0	0	0	14	0	19.9
	435	3	1	0	2	4	1	0	0	0	0	40.1
Total	24	24	4	2	2	22	3	1	1	81	0	134.0

MONTHLY TEAM UTILIZATION

TEAM #	25	26	27	28	29	30	31	Total	Days	Hrs Flown
6	4	4	2	1	23	2	2	85	85	162.3
7	24	5	1	4	23	5	3	66	66	133.0
8	21	2	1	0	19	4	3	98	98	111.0
9	19	3	1	1	17	2	1	80	80	178.6
10	35	5	2	2	30	3	3	64	64	172.3
11	24	6	2	2	22	3	3	81	81	134.0
Total	147	23	9	10	134	19	12	474	474	862.8

43d Bomb Wing - December 1968

KC-135 SCHEDULING DEFECTS AND ACCOMPLISHMENTS

1. The information that follows is an extract from the I-SAC-082 Report and reflects the KC-135 activity for December and the preceding 6 months:

	JUN	JUL	AUG	SEP	OCT	NOV	DEC
Serries Scheduled	94	84	101	114	99	80	84
Serries Cancelled	16	7	24	19	19	9	16
Serries Added	17	25	22	12	11	7	12
Serries Airborne	95	102	99	109	91	78	80
Serries Early/Late	10	9	17	6	8	13	12
Serries On Time	85	93	82	101	83	65	69
Air Accnts	0	2	6	1	0	2	1
Hours Flown	399	444	429	450	447	424	392
Average Serrie Length	4.2	4.4	4.3	4.2	4.9	5.4	4.9

2. The schedule deviation causes for December were:

	AUG	LAKE	CAWK	TOTAL
FAA	3	2	2	2
Weather	6	3	10	19
SAC	2	1	1	3
Operations	1	5	3	9
Material				
Receiver/Marker		1		1

3. Material deviations for December by system:

Instrument	1 Late Take Off	Air Condition	1 cancellation
Power Plant	2 Late Take Offs	Fuel System	1 cancellation
Else Pwr Sup	2 Late Take Offs	Auto Pilot	1 cancellation

4. The 5 Material Late Take Offs by cause and tail number:


- 1510 4 Dec MB-1 Gyro inoperative, off flag failed. Removed and replaced displacement Gyro
- 0329 13 Dec No ignition Nr 1 engine. Repaired broken wire in harness
- 1462 16 Dec Generators won't come on line. Faulty lock on relay. Repaired lock on relay
- 0339 20 Dec Nr 3 fuel flow transmitter inoperative. Removed and replaced fuel flow transmitter

434 Bomb Wing - December 1948

- 0343 23 Dec Nr 1 Generator reads low. Removed and replaced Nr 1 Freq and load control
5. The 3 Material Cancellations by cause and tail number:
- 0344 2 Dec Start Cart Air dumping in cabin. Removed and replaced emergency auxiliary heat and pressure valve
- 1452 4 Dec 3-4 Compass in error. Removed and replaced 3-4 Servo Amplifier Assy
- 1456 16 Dec Nr 4 Main Fuel Tank leak
6. The 1 Air Abort by cause and tail number:
- 1410 9 Dec Nr 3 Engine Oil Pressure Flux, Engine shutdown at 35 PSI. Removed and replaced 4 $\frac{1}{2}$ Carbon Seal

436 Bomb Wing - December 1968

AC-119G MONTHLY RATES



SOURCE: Aerospace Vehicle Status Report, FCN 22006A

434 Bomb Wing - December 1968

KT-135 NORM

1. The NORM rates exceeded the DOD standards for the second consecutive month. The unscheduled maintenance rates decreased from November, however, this decrease was off set by an increase in phased inspection rates.


2. The high NORM systems and components within each system were:

SYSTEM	HOURS	COMPONENTS	HOURS
Jet Engine	297	Power Plant	53 hours
UMP Communications	168	Breather Pressurization Valve	48 hours
Airframe	158	RT-262/AE 24	168 hours
Landing Gear	155	Access Panel	158 hours
Hydraulic	134	Rose Tires	78 hours
Radar Nav	134	Main Tires	39 hours
		Hydraulic Pump	37 hours
		Coil-Connects	25 hours
		Computer Control	24 hours
		Electronic Control	24 hours
		Amp	24 hours
		Flexible Wave Guide	20 hours

3. Hours processed on the I-HAF-A1 Report were 9577. Of these, 1048 were reported Not Operational Ready due to maintenance. Phased inspection consumed 791 of these. The requirements to accomplish multiple phased inspections prior to deploying aircraft to forward bases naturally will cause a high phase rate. This requires close monitoring of unscheduled maintenance to keep the NORM rates within standards.

43d Bomb Wing - December 1968

R-58 NORM RATES



434 Bomb King - December 1968

E-58 NORM

1. The E-58 NORM rates are above DOD minimum for the third consecutive month and for 6 of the 9 plotted months. The 25.1 percent represents 6302 hours and total of 744 hours for the month, equates to 8.5 aircraft for the entire month.


2. NORM hours were reported against 20 systems with 8 of these 20 having more than 200 hours. These systems and the high NORM components within the system were:

SYSTEM Name Nav	HOURS	COMPONENT	HOURS
	1127		
Fuel System	831	FWSU	277 hours
		Astro Tracker Telescope Assy	96 hours
		ICU	72 hours
		Frequency Tracker	66 hours
		Aft Tank Indicator	106 hours
		Quantity Totalizer	79 hours
		Boost Pump	73 hours
		RT Indicator	116 hours
		Starter Air Doors	67 hours
		Spoke Actuator	55 hours
		AC Generator	177 hours
		Decoupler Assy	152 hours
		Decoupler Shaft	66 hours
		Mr. 3 Engine Pump	72 hours
		Primary System	72 hours
		Quantity Transmitter	70 hours
		Throttle Control Valve	96 hours
		Cabin Pressure Safety Valve	69 hours
		Cabin Pressure Regulator	53 hours
		Aft Tank	106 hours
Airframe	288	Aft Tank	41 hours
Landing Gear	213	Main Tires	38 hours
		Nose Gear Door	30 hours

3. Unscheduled maintenance continues to be the area causing high NORM rates. Phased inspection is not a problem at this time.

43d Beah Ming - December 1968

1968-69 CAMPAIGNIZATIONS



SOURCE: HCS: 1-040-082
AF Form 991

42d Bomb Wing - December 1968


B/7B-58 CAMPAIGNIZATIONS

The following is a list of items campaignized showing the number of times and the reason for campaignization:

PN	COM	REASON	CURRENT	TIMES CANN'D	LAST	PREVIOUS
6610-816-1709	Fuel Flow Ind	To Prevent MOHS	1	0	0	0
1660-666-2080	Mod Valve	To Prevent MOHS	2	0	0	0
6680-886-4183	Transmitter	To Prevent MOHS	3	1	0	0
6615-850-0050	App Computer Assy	To Prevent MOHS	2	0	1	0
6615-850-4734	YACA	To Prevent MOHS	1	1	0	0
6685-473-7946	BIT Indicator	To Prevent MOHS	1	1	0	0
6610-530-3074	Indicator	To Prevent MOHS	2	0	0	0
1660-850-7735	Cold Air Valve	To Satisfy MOHS	2	0	0	0
1660-661-2475	CSP Shaft	To Prevent MOHS	1	0	0	0
473-71-7394X	Coupling	To Prevent MOHS	1	0	0	0
1660-770-0047	Valve	To Prevent MOHS	1	0	0	0
5930-683-4909	Switch	To Prevent MOHS	1	2	1	0
1660-675-2947X	Simulator	To Prevent MOHS	1	0	0	0
1680-070-5969	Mixing Harness	To Prevent MOHS	1	0	0	0
5895-962-4584	T-4 Power Amp	To Satisfy MOHS	1	0	0	0
5895-545-5382	T-4 Antenna	To Prevent MOHS	1	0	0	0
5895-545-5374EM	T-4 Driver Amp	To Prevent MOHS	1	0	0	1
2915-863-1321	Valve	To Prevent MOHS	1	0	0	0
1680-343-5745	Amplifier	To Prevent MOHS	1	0	0	0
473-576-1825	Hose Assy	To Prevent MOHS	1	0	0	0
473-590-8174	Hose Assy	To Prevent MOHS	1	0	0	0
1660-666-2080	Valve	To Prevent MOHS	1	0	0	0
		Satisfy MOHS	1	1	0	0

433 Bomb Wing - December 1968

EC-135 CAMPAIGNIZATIONS



SOURCE: HQS: 1-SAC-082
AF Form 991

434 Bomb Wing - December 1948

HC-136 CANNIBALIZATIONS

The following is a list of items cannibalized showing the number of times and the reason for cannibalization:

P/N	QTY	REASON	TIMES CANIB	
			CURRENT	PREVIOUS
6012-550-6628	Cyro MDI	To Prevent NCRS	1	0
6600-772-8567	Power Supply	To Prevent NCRS	1	0
6110-915-3093	Panel	Maint Convenience	1	0
6020-578-852	Fuel Flow Trans	To Prevent NCRS	1	0

424 Boko Ming - December 1968

REPEAT NUMBER - IFS, B-52

1. There were 134 sorties flown with repeats occurring on 74 sorties. They range from 1 to 5 per sortie as follows:
 1 Repeat on 48
 2 Repeats on 15
 3 Repeats on 9
 4 Repeats on 1
 5 Repeats on 1
2. The reliability code distribution on the repeats was 69 code 2, 44 code 3 and 1 code 5. The distribution of the repeats by system are as follows:

SYSTEM	CODE 2	CODE 3	SYSTEM	CODE 2	CODE 3	SYSTEM	CODE 2	CODE 3
Engine	2	0	Doppler	2	7	Auto Pilot	7	1
A/C Press	1	1	b/N	32	0	IFF Radio	0	1
A/Radio	5	0	ECM Rec	3	0	Oxygen	2	0
EG Gear	2	0	Tacan	0	1	Radar Alt	1	0
Hydraulic	1	0	Elec Pwr Sup	0	3	IFF	0	1
Compass	0	2	Fuel (Onset)	9	0	ECM Trans	0	8
IFF	1	0	IFF Radio	1	1	IFF Radar	1	0
IIS	1	0						

3. There were 2 repeat code 3 that were code 2 on the previous sortie. These repeats were on the following systems:

SYSTEM	REPEATS	SYSTEM	REPEATS
Auto Pilot	1	Compass	1
Radar Alt	1	Tacan	1
Doppler	1	IFF	1
b/nav	1	Air Conditioning	1

4. There were 36 repeat code 3 that were code 3 on the previous sortie. These repeats are on the following systems:

SYSTEM	REPEATS	SYSTEM	REPEATS
IFF Radio	1	Compass	1
Radar Alt	5	Doppler	6
Elec Pwr Supply	3	Nav	5
IFF	2	ECM Trans	8
ECM/Nav	5		

5. The repeats followed the normal system pattern with 78.9 going to the electronics area. This is the case in both code 2 and 3 repeats.

43d Bomb Wing - December 1968

REPMA...ITE-IFS P-68

1. There were 134 sorties flown with repeats occurring on 74 sorties. They range from 1 to 5 per sortie as follows:
- 1 Repeat on 48 3 Repeats on 9 5 Repeats on 1
 2 Repeats on 15 4 Repeats on 1
2. The reliability code distribution on the repeats was 69 code 2, 44 code 3 and 1 code 5. The distribution of the repeats by system are as follows:

SYSTEM	CODE 2	CODE 3	SYSTEM	CODE 2	CODE 3	SYSTEM	CODE 2	CODE 3
Engine	2	0	Doppler	2	0	Auto Pilot	7	1
A/C Pres	1	1	H/W	32	6	HF Radio	0	1
A/Refuel	3	0	BOM Rec	0	0	Oxygen	2	0
L/D Gear	2	0	Tacan	0	1	Radar Alt	1	0
Hydraulics	1	0	Elec Pur Sup	0	3	Nav	1	5
Compass	0	2	Fuel (Other)	9	0	BOM Trans	0	0
IFF	0	2	HF Radio	1	1	FSC Radar	1	0
ILS	1	0						

3. There were 8 repeat code 3 that were code 2 on the previous sortie. These repeats were on the following systems:

SYSTEM	REPEATS	SYSTEM	REPEATS
Auto Pilot	1	Compass	1
Radar Alt	1	Tacan	1
Doppler	1	HF	1
B/Nav	1	Air Conditioning	1

4. There were 36 repeat code 3 that were code 3 on the previous sortie. These repeats are on the following systems:

SYSTEM	REPEATS	SYSTEM	REPEATS
HF Radio	1	Compass	7
Radar Alt	5	Doppler	0
Elec Pur Supply	3	Nav	5
IFF	2	BOM Trans	8
Bomb/Nav	5		

5. The repeats followed the normal system pattern with 78,9 going to the electronics area. This is the case in both code 2 and 3 repeats.

43d Bomb Wing - December 1968

6. The following aircraft had more than one repeat write-up on a single system during the month of December. The aircraft tail number and repeat system are listed below:

ACFT #	DATE	SYSTEM	DATE and REPEAT #
1013	3 Dec	Auto Pilot	2 2
	5 Dec		1 1
	9 Dec		3 3
1018	3 Dec	Auto Pilot	1 2
	5 Dec		2 1
	10 Dec		3 1
1019	18 Dec	Radar Altimeter	2 3
	20 Dec		3 1
	26 Dec		3 2
2433	12 Dec	Radar Altimeter	2 2
	16 Dec		3 1
	20 Dec		3 2
2439	13 Dec	Doppler	2 2
	17 Dec		3 1
2439	19 Dec	Bomb/Nav	2 2
	23 Dec		3 2
2444	17 Dec	Electric	2 2
	19 Dec		3 3
2445	17 Dec	Bomb/Nav	2 3
	23 Dec		3 2
	26 Dec		2 2
2455	30 Dec	Doppler	2 2
	4 Dec		3 3
	6 Dec		4 1

434 Bomb Wing - December 1968

WORK CENTER	MANHOOR UTILIZATION				TOTAL			
	E-38	FOD	MC-130	BE/WR		AGE	SUPPLY	OTHER
22101	1365	92						1457
102	1363	6	4					1373
103	1476	21	1					1501
104	1574	49						1623
105	1105	14	4					1123
106	1174	24						1198
107	1741	10	12					1863
108		11	134					145
111		2	1278					1280
185	2001		1231	234				3466
188	2001		22					2023
310				1871				1871
311				1028				1028
322	310	17		1803				2130
Total	12901	207	4226	4734	824	14		19376
24110	1326	8	387	57	25	152	17	2064
122	473		386	91	4	42	16	1318
125			260	1		3	43	307
131	1269	3			96	71		2039
210	1026				140	62		1228
310	4160	4			8	271	76	4513
320	1724				15	42	10	1791
331	22				139	47	6	405
400	431	10						441
500								441
TOTAL	11371	25	1172	196	297	815	2494	16370
TOTAL	47170	2128	11893	6153	9948	3127	6253	86672

SOURCE: Report 3-1. The figures portrayed indicate the manhours documented on AFTO 349's. There were 21 working days during this month. 32

43d Bomb Wing - December 1965

WORK CENTER #	SHEP	MANHOUR UTILIZATION						TOTAL		
		B-58	POB	KC-135	BF/TR	AGE	SUPPLY	OTHER		
23110	Machine	1015	55	264	23	153	271		1761	
130	Welding	187	3	61	26	478	398	3	1156	
130	Struct Rep	1311	27	407	88	94	166		2863	
150	Survival Equip	6							930	
155	Fabric	63	2	13					527	
160	Corr Cont	390		222	35	136	34		811	
170	NDI	213	2	6	19	76	9		324	
210	Recip Engine				519	32			551	
220	Prop Shop				16				16	
230	Jet Engine	3134		2996	317	374			6821	
210	Aero Rep	962		308	4	9			1283	
220	Fuel System	1004	23	515	1	2			1723	
230	Electric Shop	1622	5	345	136	162	36		2315	
340	EW/EI	3249		623	44	290	4		4176	
220	Instrument	2237	102	187	9				2935	
300	M/A	1929	51	168	4	49			2211	
270	Mech/Tire	955		177	4	107	12		1255	
280	IFR	55		149					224	
290	Press	1567	5		11	9			1592	
710	AGE Repair/Inst	11				2676			2687	
420	Service					2087			2087	
430	Pull/Delivery	5				854			859	
TOTAL		19997	473	6451	1223	7445	2238	355	38242	
25110	B-58 CO & I	1851	536			6			2487	
120	Weapon Rel		298	2		1175		2	1477	
210	Nuclear Wp	25	511	4		11		1521	2072	
230	BOD Conv	17	18	8		55		700	798	
250	Re-Entry					124		987	1111	
TOTAL	M/S	1893	1363	14		1371		3404	8645	

B-58 POST MODIFICATION
AIRCRAFT PERFORMANCE
REVIEW

15 - 16 October 1968

Little Rock AFB, Arkansas

1. The review was convened by SAAMA, 0900, 15 October 1968 in B-362, AEMS Conference Room with representatives from SAC, WRAMA and contractors in attendance. A list of attendees is provided as Atch 1.
2. Colonel Lewis Williams of SAAMA opened the meeting and outlined the Agenda to be followed. The purpose of this meeting is to review the performance of modified aircraft received from the Mod Site (GD/Waco). This included a discussion of problems associated with Mod 882, 1588, 10002 and 10003.

(OLD BUSINESS)

3. Data on Action Items from Previous Meeting
 - a. LRU Quality
 - (1) Dog LRU'S: Funds required for contractor repair of "Dog LRU'S" were approved by Headquarters AFIC on 2 Oct 1968. WRNN initiated urgent Purchase Request for repair of these LRUs on 4 Oct 1968. Target for repair contract award is 29 Nov 1968. WRNN will report progress to all concerned on 31 Oct 1968.
 - (2) Alignment procedures at GD/Waco: SANEP directed the DCSAR on 24 Sep 1968 to assure the contractor uses RLRUTS when alignment of RYM and PRU is required.
 - b. Overheat Problems
 - (1) Sperry will provide 43rd and 305th Bomb Wings a plan for installation of temperature sensitive tapes and a quantity of tapes required to monitor ten aircraft at each Wing. Tapes and plan will arrive at Wings on or about 31 Oct 1968. Confirmation of tape ranges selected should be achieved by 30 Nov 1968. At that time Sperry will take action to obtain tapes for remaining aircraft. These additional tapes will be furnished the Wings by 16 Dec 1968. Bomb Wing assistance will be required to install, read, record and report tape readings.
 - (2) Investigation of ARU overheat on aircraft at Little Rock AFB indicates 3 failures attributed to pressure regulator valve in cold air duct, 1 to warm air valve control and 1 to broken temperature sensor. Confirmation of failures at Grissom AFB has not been received. Present

phased inspection requirements for warm air control and temperature sensor are considered adequate. However, SAAMA will recommend adding operational check of the pressure regulator valve at the next Maintenance Management Review. A fact finding team will convene at Grissom AFB, 16-18 Oct 1968, for further evaluation of the problem.

4. Wiring and Harness Problems

a. Nav Chassis

(1) A decision has been made to rehabilitate problem Navigation Chassis Units identified by SAC at Depot level rather than at Grissom AFB or GD/Waco as discussed during the 11-12 Sep 1968 Mod 10003 Review at Grissom AFB. It is estimated that 40-manhours, in addition to the current Depot repair standard, will be required to rehabilitate each problem Navigation Chassis.

(2) WRAMA implemented the Navigation Chassis rehabilitation program at SAAMA on 26 Sep 1968.

5. Navigator Training

All GFE for Bomb/Nav mission simulator is available at Curtiss-Wright Corp. Prototyping is in progress at Grissom AFB. Final retrofit installer is expected to be completed in Dec 1968.

6. Items Outside MOD 10003

a. TCTO 1B-58A-827 has been issued to correct the wiring error in Mod 887 (Cartridge Starter). Thirteen aircraft are affected and all have been completed.

ACTION: (1) SAC will advise SANB of training requirements,

(2) SANBR will notify SAC when adequate supply of cartridges will be available.

b. LARA wiring discrepancies have been brought to the attention of the Contractor and DCSAR. DCSAR surveillance of installation has been initiate

c. Contractor assistance has been provided to Grissom AFB to resolve Flight Control Tester problems. The Tester has been made operational, modified ACA and new YACA box were checked out on Tester. The Tester is now functional. RYD modified aircraft have been experiencing what appears to be excessive yaw damper caution light illumination. Additional flight experience must be obtained to determine if tolerances require changing. YACA monitor tolerances must be kept tight, otherwise their purpose would be defeated.

ACTION: SANBT will investigate yaw rate to roll and yaw caution light problem to determine if actual malfunctions exist during illumination. Method of investigation and target date for completion will be provided by 30 Oct 1968.

d. In order to provide AFLC with additional information concerning Bomb/Nav System performance, SAC will report significant in-flight discrepancies on the first five sorties following aircraft delivery. SAAMA will evaluate the data and initiate any required corrective action.

e. All PRU cameras received at the SRA (OOAMA) are being overhauled. Adequate assets are on hand and no problems are anticipated in supplying assets to meet the modification schedule.

7. MOD Power Supply

Investigation of Mod Power Supply problems are continuing at Raytheon and Litton.

ACTION: WRAMA will provide a status report on the progress of efforts to solve problems with modified Mod Power Supply by 31 Oct 1968. This report will include results and recommendations of the WRAMA/Raytheon investigation of the failed A-1 and A-2 diode stacks, magnetron operating current and interface problem between the magnetron and MPS.

8. Tech Data Shortage

a. SAAMA provided available copies of 33 and 5 series TOs to 43AEMS on 17 Sep 1968 together with pertinent information concerning availability

of the remainder. Formal copies of 118 Series Technical Orders required by SAC were shipped from WRAMA on 10 Sep 1968. Formal distribution of TO 12F5-4-54-2 is scheduled for November 1968.

b. SAC indicated numerous errors are in 33 Series Technical Data changed by Mod 10003. The entire spectrum of 33 series TOs requires post publication. Specific TOs having errors too numerous to follow normal APTO Form 22 procedures are:

33D7-14-4-8	33D7-14-4-1	33D5-8-54-4
33D7-14-4-4		33D5-8-54-2
33D7-14-4-2		33D5-8-54-1

The deadline for correcting deficiencies under contract warranty is 31 Oct 1968. All changes to Mod 10003 date must be documented through WRAMA (WRPIF) prior to this time.

ACTION: SANB will contact SANR and attempt to arrange for a post publication review.

9. LARA zero, blanking pulse, termination and tracker calibration cables are local manufacture IAW TO 12F5-4-54-2. To assure proper date was available, additional copies of manufacturing instructions were provided to SAC bases 26 Sep 1968. (Connectors are local purchase items.)

(NEW BUSINESS)

10. MOD 887 (Self Start Capability)

Manufacturer of Gearbox Drive is unable to meet the delivery schedule therefore, SAMMA will only be able to provide kits to modify the #2 engine.

ACTION: SANBP will notify SAC as soon as possible of the date modification can be resumed to include all four engines.

11. MOD 1588 (LARA)

Investigation of antenna problem is continuing. As an interim measure, the antenna will be installed at GD/Waco and the system checked out. The

antenna will then be removed and a plate installed. The antenna will be delivered to SAC with the aircraft.

ACTION: SANBT will provide a progress report by 15 Nov 68.

12. MOD 10002

Failures have increased on new RG&A. Lack of spares support is causing cannibalization.

ACTION: SAAMA will apprise the IM of the problem and request an investigation be conducted.

13. MOD 10003 (Bomb/Nav)

a. Dr. Kirby (Sperry WSIG) presented a status report of all Code 3 faults occurring on modified aircraft and an analysis of the failure trends. One of the basic problems is repeat write-ups. This is caused primarily by lack of serviceable spares. WRAMA's action to repair the identified problem LRUS is expected to alleviate this problem. Future identified LRUS will be cycled thru the SPA for complete overhaul under a special Depot project.

ACTION: WRAMA will investigate possibility of authorizing the contractor to modify spare LRUS presently on hand at Sperry in order to expedite overhaul of Dog LRUS. WRAMA will be action agency to provide specific type canine LRU's to Sperry for repair and return to SAC. WRAMA will select LRUs by serial number and provide SAC a replacement spare in those cases where the "Dog LRU" to be repaired is a SAC spare. Mr Mullaney (WRNNR, Ext 5314) will direct all "Dog LRU" shipments.

b. SANB has received an unsolicited proposal from Sperry Corp concerning purchase of flat harness for the field maintenance shops.

ACTION: SAAMA will evaluate the proposal to ascertain if time and cost allows obtaining this capability.


c. A discussion of spares support ensued. WRAMA requested SAC provide a list of Bits and Pieces required to repair their AWP items. Included in this

list should be those items that experience dictates will be troublesome to obtain.

ACTION: 43BW requirements are listed on Atch 2.
305BW requirements will be provided
WRNRR (Mr Tom Mullaney) by 22 Oct 1968.

14. Mr Mullaney (WRAMA/WRNRR) reported on the results of the spares review. A spares delivery schedule is provided as Atch 3. SAC (DM3P) has authorized Priority 2 requisitions on LRUs and spare parts to support Modification 10003. Followup action will be provided by SANER. SAC (DM4D) will investigate possibility of obtaining priority action on spares support for MOD 10002.

15. WRAMA/WRNN will advise all concerned by 31 Oct 1968 current status MOD 10003 field AGE support due in from Raytheon, Sperry and SMED. Information will cover kits required to modify spare modules and provisional spare parts.


 100071000
 DEPARTMENT OF THE AIR FORCE
 HEADQUARTERS, WASHINGTON, D. C. 20330
 30 OCT 1968


SANB

Status of Action Items - B-53 Post Modification Aircraft Performance
 Review 15-16 Oct 1968

825 Strat Aerosp Div (DM)
 Little Rock AFB
 Jacksonville AR 72076

1. Reference is made to the minutes of subject post modification review.
2. The following comments are provided on para 6 concerning investigation of reported yaw rate to roll and yaw caution light illuminations:
 - a. A review was conducted of SAC Form 126 data and APP 66-1 failure data for period covering RYO flight experience. The review revealed a number of repeat Light Illuminations and Yaw Amplifier Computer Assembly (YACA) box/module failures. However, this information could not be correlated to identify the cause, if any. SAC assistance may subsequently be required to identify repeat offender aircraft, results of system trouble-shooting; and providing failed components for analysis.
 - b. ASD, as ORR for the RYO system, has been advised of the above condition and requested to investigate same. Method of investigation and target date for completion will be provided as soon as it is developed.
3. The following comments are provided on para 12 concerning new Rate Gyro and Accelerometer (RGA) reported failures:
 - a. APP 66-1 failure data for Jul-Sep 1968 revealed only one actual failure of the modified (new) RGA, Part No 19914.
 - b. A review of our supply information does not reveal any spaces/cannibalization problems on this item. No further action can be taken until detailed specifics are provided.

FOR THE COMMANDER


 ARTHUR G. CHAFFEE
 Deputy Chief, P&S/CEA/T-70, SM Div
 Directorate of Material Management

COPY

DEPARTMENT OF THE AIR FORCE
HEADQUARTERS SECOND AIR FORCE (SAC)
BARKSDALE AIR FORCE BASE, LOUISIANA 71110

REPLY TO
ATTN OF: C

SUBJECT: B-58 Post-Modification Aircraft Performance Review - 15-16
Oct 1968, Little Rock AFB (Your Ltr, 23 Oct 1968)

TO: 825 Strat Aerosp Div (C)

My Materiel staff will closely monitor the problem areas outlined in your letter. Please insure that all possible actions are taken by your units within their capability to improve the reliability of the modified aircraft.

s/v/
A. J. RUSSELL, Lt General, USAF
Commander

24 OCT 1968

C

1-40 Test, Evaluation, Acceptance Performance Review -
12-10 October 1961, Little Rock AFB

Lieutenant Colonel A. J. Russell
Commander, Second Air Force
Ft. Belvoir AFB, Ia 71110

Dear General Russell:

1. The record of P-53 systems, location, occurrence and date (15-4 October 1968 at Little Rock Air Force Base). The information included, in addition to a list of all P-53s, will all information in 1-40, problem encountered as outlined in that section, and a statement you make as to whether you are satisfied with the aircraft maintenance program. Progress and in areas of any concern 16 September in this subject is as follows:

a. Line 3 aircraft (1-10) (Cully, Warner-Robins Air Materiel Area (La. 3-000, Warner-Robins) which was required for a structural repair of "40, 1000" or "10" was recovered by A-1 on 2 October 1968. Repair contract would be completed by 15 October 1968.

b. Air Conditioning/Overhaul Problems: Supply will provide a plan for installation of two pressure sensitive tapes by 31 October 1968. Tapes and pins will arrive at the shop on or about 20 October 1968. Components of two P-53s which are to be addressed by 30 November 1968. The shop will select and install the components in an effort to decrease the number of overhauls. The team from Warner-Robins Air Materiel Area (ARMA) will be on site at the auxiliary reference unit "vertical" problem for part of the team to Grissom Air Force Base 16-18 October 1968. An evaluation.

c. Harness and Wicket: Although the 16-18 October 1968 team established a navigation unit check at IRAS Program was not completed, Warner-Robins Air Materiel Area (ARMA) was decided to establish

a rehabilitation program at depot level. It is estimated that 40 manhours, in addition to the aircraft jet repair manhours, will be required to rehabilitate each problem navigation unit chassis.

d. LRU Storage: WAAHA requested SAC provide a list of spare and pieces" required for repair of AWP Items. SAC (LW 31) has authorized Priority 2 requisitions on LRU's and spare parts to support modification 10005. SAC will investigate the possibility of obtaining priority actions to expedite support for modification 10002. WAAHA (Mr. Sullivan, WHITFIELD) will advise SAC concerned by 31 October 1968 on status of modification 10003 which also support due in from Raytheon, Sperry and Sperry Metrowave Electronics Division.

2. New items of discussion and problems encountered are as follows.

a. Low Altitude Radar Altimeter: Anomalous indications of the Improved Radar altimeter appears to have resulted coincidentally in the extent that antennas have departed the aircraft in-flight on several occasions. As an interim measure, the antennas will be installed at General Dynamics/Waco and try them there. The antennas will then be removed and a plate installed. The antenna will be returned to SAC with the aircraft. It is possible Honeywell has enclosed a "tip" in the form of a "backed up" antenna, which should be available in the field by mid-December, thus solving this problem.

b. Redundant Yaw Damper: The redundant yaw damper installed aircraft have been experiencing what appears to be excessive yaw damper caution light illumination. The possibility of excessive tolerances exist; however, because the tolerances would defeat the purpose of the modification, SAAHA (ANNETT) will investigate the yaw rate to roll and yaw caution light problem to determine if an actual malfunction exists. Method of investigation and target date for completion will be provided by 30 October 1968.

c. Cartridge Start: The vendor of the gearbox drive is not able to meet the delivery schedule. Therefore, SAAHA will only be able to provide modification kits for the 32 engine. SAAHA (ANNETT) will notify SAC as soon as possible of the resumption of modifications to include all four engines.

THIS DOCUMENT IS NOT RELEASABLE AS AN ORIGINAL

(S) (1) (B)



CLASSIFICATION		UNCLASSIFIED	
CONTROL		UNCONTROLLED	
REF ID	INDEX	SEARCHED	SERIALIZED
	X		
PRECEDENCE			
PRIORITY			
FROM: SAC, TULSA AFB TUL			
TO: SAC /WAB/ (REPORT DELIVERED)			
INFO: OCAF /SAPIS/ WASH DC			
COMAF /ARDE/			
DIR OF ARMOR SAVTY /ARSA/			
MOTION AND CALIF			
AFPO /CEN/ GEN DYNAMICS/FT WORTH TX			
AFIC /MOTA/NCIS/			
OCMA /COSU/ TINKER AFB OKLA			
OCMA TINKER AFB OKLA			
COMA HILL AFB UTAH			
SHAWA MCCLELLAN AFB CALIF			
WASA ROBINS AFB GA			
AFSC /SOCHI/			
ASD /AS/ WPAFB OHIO			
DET 3100 33465DTWNSQ BATTLE ROCK AFB ARK			
DET 2170 33465DTWNSQ CHICKEN AFB ARK			
325TRAIAR002DIAV /DIA/30CM/			
LITTLE ROCK AFB ARK			
305BONDNG /DCI/ CHICKEN AFB IND			
DATE	1	1	1
REPLY	067		
DATE			
SIGNATURE			
B. G. Smith			
305BONDNG			
DATE: 11/13			

359

AIRCRAFT ENGINE ASSEMBLY FORM ORIGINATOR'S CONTRIBUTION SHEET		DRAWN BY DATE
TITLE PROJECT	RELEASED BY DATE	DRAWN BY DATE

W.P.S. ETO: EAK

THIS IS WORKING DRAFT AND UNUSUAL INTERIM: THIS COMPLIANCE

TECHNICAL ORDER (A-3-A-831 DT) IS OCT 69 DATA (DE 012-837.

SUBJECT: Installation of Low Altitude Radar Altimeter (LARA).

1. Application

a. This technical order is applicable to certain B-50A aircraft modified by TO 13-58A-017 4 Apr 69. Mobile training sets are not affected.

b. This work shall be accomplished on the following aircraft:

B-50A Serials 58-1010, 58-2440, 58-2444, 58-2449, 60-1110,

60-1111, 60-1113, 60-1116, 60-1115, 60-1117, 60-1121 through

60-1127, 61-2025, 61-2029, 61-2040, 61-2044, 61-2046, 61-2072,

61-2075, 61-2078, 61-2080.

2. Purpose - This technical order removes LARA antennas to prevent damage due during flight.

3. When to be accomplished - Not later than ten days after receipt of this technical order. Failure to accomplish the work by the expiration date shall result in discontinued area of affected systems. The work required herein will be accomplished.

APPROVED FOR RELEASE
 DATE 10/15/69
 BY SP4/MLC/...
 2 5
 UNCLASSIFIED ETO

ASSOCIATED JOB: REVISIONS

and/or COMMENTS: REVISIONS

RELEASER OF INFORMATION: REVISIONS

DATE: 11/10/88

BY: REVISIONS

5. What is required.
- a. Supply information and requirements:
- (1) Kit required: Not applicable.
 - (2) Action required on items in stock: Not applicable.
 - (3) Parts required to modify items in stock: None.
 - (4) Disposition of removed and replaced parts: Return to supply organization.

(5) Drawings required: None.

(6) Size, weight and cost of kits: Not applicable.

(7) Disposition of kits: Not applicable.

b. Personnel information and requirements:

Work Phases	REQ Skills	Manhours Required
Isolate Power	Acft Electrician	0.25
Remove Antenna	Acft Electrician	0.50
Install Cover Plate	Sheet Metal Tech	2.25
Tools & Materials Required (Estimated)		3.00

- c. Special tools, jigs, fixtures required: Not applicable.
- d. How work will be accomplished & Warning: Insure all existing safety procedures are complied with.
- e. Remove 728 Volt DC, 5 amp fuse labeled ICH AIR MAIL 1140 Power Panel, 3rd Station.

11/10/88

REVISIONS

11/10/88

REVISIONS

11/10/88

REVISIONS

UNITED STATES JOINT CHIEFS OF STAFF
 MESSAGE FORM
 NO. 1
 CONTINUATION SHEET
 UNCLASSIFIED

REL. INFO BY: []
 CONTROL BY: []

b. Remove the each IAW antenna. Install dust covers on co-ax end and antenna connectors. Secure co-ax cable to circuit. Exchange screws.

c. New plates and shims as follows:
 Shim (2 ea) - .060 X 5.55 X 6.22 2024-T31, -536, -23 or 744.
 Shim (2 ea) - .060 X .50 X 5.50 material as above.

Shim (2 ea) - .060 X .50 X 3.00 material as above.
 Locate holes from antenna housing. Drill holes .187 + .001 - .010 dia and countersink .328 + .051 - .000 dia by 62° ± 2°.

Install plate and shims using existing screws (Part No 615.8-2).
 Screws shall be sprayed with zinc chromate primer prior to installation.

7. Supplemental information.

- a. Operational checkout requirements:
 - (1) Operational check flight required prior to return for normal operation.
 - (2) No directional checkout of affected circuit is required.

b. Weight and balance information: The weight and balance change resulting from the instructions contained herein is negligible.

UNCLASSIFIED INFO

18 APR 1988

5

UNCLASSIFIED INFO

RECEIVED AND CONTINUATION SHEET		DRAFTED BY
PROJECT NO. 	TITLE 	DATE

c. Technical manuals affected: Not applicable.

d. Records:

1. Action required on maintenance records. AFM Form 349

(9-24) SC reporting.

2. Action required on supply records: None.

NOTE: Will analyze this to LW TD 00-5-1. This message forwarded to action addresses for dissemination to all affected activities near your administrative surveillance.

15 5 500 / 8 7
 15 5 500 / 8 7
 15 5 500 / 8 7

7-11-68
4000
845 DM
B.C.

Comms/Techs Annex and Inmate/6477
6 NOV 1968
B-38 heading navigation system heading knob modification

7-11-68
4000
845 DM
B.C.

Request for Class II modification submitted in accordance with
Table 4, Table 1, AFM 57-4, on B-38 heading knob.

1. heading knob, part number 67160-4, stock number 1280-897-6477
in the B-38 heading navigation system installed on B-38 aircraft.

2. When the Primary Navigation Stabilization Unit (PNSU) and
Auxiliary Reference Unit (ARU) become insensitive in flight, all
synchronous heading capability is lost because of loss of heading and
velocity references. This modification will provide a malfunction
mode which will give accurate heading and velocity references with the
aid of the insensitive or unusable, thus providing synchronous
heading. Heading is computed by diverting Error Psi, through relay
circuitry, to the heading knob, from Psi in the PNSU and ARU. Then, Error
Psi (this value) is inserted, through relay action, into the Psi
error in heading knob on the basis that was the source Error Psi input
to a register. The error theta (this value) signal is dispersed
and to theta heading - theta B. This and result provides a correct
psi valve theta heading signal in the computer, which is fed to the
circuit in the heading knob. Velocity is computed by resolving the
error about Psi in the same manner as air speed inertial. The output
of the Psi shaft is resolved, through relay action, is routed to the
theta B/theta A resolver. This results in a psi and theta in the
system that is of the same accuracy that is now available in airspeed
error. Psi and theta are fed to the remainder of the associated
circuitry in the heading knob.

3. Subject modification request was initiated to increase the
reliability and mission effectiveness during first sortie after Board
Case (PNSU) profile, and other training sorties by providing
synchronous heading capability when the PNSU and ARU are inoperative
or unusable.

4. Serial 6 each, P/N 5905-66-001, source in Force stock.
Title serials are each, P/N 5900-013-0030, source Air Force stock.
The equipment involved is primary.

- e. The 43d AEWB Bn/aw Shop can accomplish the proposed modification.
- f. This unit has 40 heading racks.
- g. No process modifying one (1) heading rack for experimental purposes.
- h. No effect on related A/E and training equipment.
- i. No additional training required. A checklist of operational procedures is adequate.
- j. This letter also constitutes request to make two operational flight tests for modification proofing.

FOR THE COMMANDER

HEINRICH G. MOSENF, Colonel, USAF O/T to: SAC (DMS)

43D Bn Commander SAC (SMA-3)

 SAC (ASST)

 30052JA

NOV 18 1950

AMMS LITTLE ROCK ARK AYA

2177

ROCK AFB ARK

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

211-0106421

ZSR 0000
 9 14190W OCT 68
 FM SHAMA RELY 45 13
 TO RUCBTB/50800WG 700W/681800M 08P 100
 RUMVFAA/95576ATA/PCSPD19 /ANNOW/ LITHE P ROLK 08A 13
 BT

UNCLAS SANS
 SUBJECT: SUPPLEMENTAL INFORMATION TO FORM 14-00A 205, RELATIONS OF
 OF FITTING COMPONENT PART NO PRO 574 777 3 82073 WITH
 FITTING COMP 0100 MADE IN AUBURNMASS WITH SPECIFICATION
 MIL 88353 TYP II CLASS I GRADE 8-2500 ON ALPAC/CA
 COMPONENTS - B-52A AIRCRAFT PODS; BOMBING MESSAGE RE PASSED TO
 DEPOT TEAMS ACCORDING TO SUBJECT TOLD IN WASHINGTON SUPPLY ROOM
 18-284-000Y FORWARDED THIS DATE FOR FULFILLATION IS ARRANGED IN
 YOUR IMMEDIATE COMPLIANCE. PARAGRAPH 5.4.13 MATERIALS, REQUIRED
 OF BASIC 1.15 IS HEREBY REVISED TO READ AS FOLLOWS:

(1) MATERIAL REQUIRED
 THE FOLLOWING MATERIAL REQUIRED TO COMPLY WITH THIS
 TECHNICAL ORDER IS NOT FURNISHED IN A TOL AND THEREFORE,
 WILL BE OBTAINED THROUGH THE APPROPRIATE SUPPLY SOURCES.
 QTY STOCK NO PART NO MANUFACTURER SOURCE

15 OCT

QTY	STOCK NO	PART NO	MANUFACTURER	SOURCE
2	6850-854-035	DCR	ACRY PRIMER GUSP LP/USA	WITH 009 CORNERS
2	6850-999-7410	55-4004	PRIMER GUSE WITH LP/USA	GENERAL ELECTRIC
2	PT NSL	TT-1-735	ALCONOL	ISOPROPYL FL
1	PT NSL	16 FA 8105-837-7754	RUBBER BAND	LP/USA
1	PT NSL	16 FA NSL	MIL-I-27730A TAPE	TYFON LP-05A
1	PT NSL	3/4 INCH WIDTH	OR SUITABLE	
1	PT NSL	8 FA NSL	SUBSTITUTE	
1	PT NSL	BT COVER		
1	PT NSL	PLASTIC		

PAGE 3 RUMVTD04182
 ONLY
 TT-1-735 ALCONOL ISOPROPYL FL
 BAS POLYETHYLENE LP/USA
 RUBBER BAND LP/USA
 MIL-I-27730A TAPE TYFON LP-05A
 3/4 INCH WIDTH
 OR SUITABLE
 SUBSTITUTE
 BT COVER
 PLASTIC
 AF STOCK
 FND

25

UNCLASSIFIED

X

ROUTINE

033/0000000000/0000000000/0000000000
 2/7/84 03/ 0000000000/0000000000
 INFO: SAC/DIA/0000000000/0000000000
 0000000000/0000000000/0000000000
 0000000000/0000000000/0000000000
 0000000000/0000000000/0000000000

1000
 1000
 1000
 1000
 1000

UNCLAS 48FCM

DURING NORMAL DUTY HOURS. SUB: E-58 FUEL LEAKS
 The purpose of this log is to update you of the current status of
 problems being experienced by 1-10 Wing with the E-58 fuel system.
 During the period 10 Oct - 21 Nov the 435th has cancelled 15
 sorties (10 and 1) due to fuel leaks. The impact of these training
 losses in CANS rated areas and their effect on the unit's EWG
 capability is sufficient to warrant concern. Normal alerting fastener
 leaks are to be expected and can be coped with. My concern is

21
 1000
 1

JAMES D. HIGLEY, JR
 COLONEL, USAF
 435 AFB COMBAT ROOM 10111

3317

83

JAMES D. HIGLEY, JR., COLONEL

ROUTINE

43DCM

UNCLASSIFIED

43DCM 3

Directed towards an excessive number of leaks that have occurred at the inboard engine pylons of the forward tank. Leaks appear to be a direct result of improper sealant applications accomplished during the recent 1000 modification. Thus far, five (5) incidents collected with the leak appearing thru the fasteners currently over the engine pylons at the outboard end of panels 17/1, 6/1-10170-3 and -5. Repair of the leak is a major task requiring:

- (1) Defuel and drain
- (2) Jack and shore
- (3) Removal of upper wing skin (500 bolts)
- (4) Remove faulty sealant
- (5) Reseal and cure
- (6) Replace skin and cure 24 hrs
- (7) Refuel and leak check

Accomplishment of these steps result in loss of the left for 5-8/10 days with work proceeding around the clock. Examination of the area indicates foreign matter, i.e., safety wire, brush bristles impregnated in the sealant and improper preparation of

43DCM

2 3

UNCLASSIFIED

88

43DCM

ROUTINE

the surface prior to application of sealant are cause for the sealant breakdown. CSMAN has been advised of our findings and CA/TW and other Engineers are scheduled to arrive Little Rock, AR 22 May to evaluate the problem. Unless the findings of the Engineers denote a re-assessment of my position, I feel that our experience on case five (5) best indicates a trend and the solution is readily present throughout the fleet. If this is the case, I recommend continuation of developing plans to re-completed the fix of the two field. You will be advised of further developments as they occur.

UNCLASSIFIED

X

ROUTINE

8257WABND08MORBY LITTS LOCK AFB ARK

2M/2MMS 8-24-68 AND 1A

INFO: SAC/D 413 CAPUTR APP 1484

CCALM/OCASAC THUR AFB OKLA

EMALY/DAWD 22LY AFB TX

8253RD/DM LAMP (BY INTERCOM)

EMERG
400
400
400
400

UNCLAS 43DCM

STAYED DURING NORMAL DUTY HOURS. SUBJECT REQUEST FOR

EMERGED DUTY, DEPOT FUEL SYSTEM RECOMMISSION

Ref Incls 43DCM 1484 600010Z Oct 68, 001400Z Oct 68 and

202204Z Oct 68. Orders for Depot Team presently in place expire

30 Dec 68. Request same team members be committed to project

for an additional ninety (90) days commencing 2 Jan 69. Previous

standing position of 424X0 personnel has not changed. Repair

requiring call entry continue to develop. Left with extensive

major maintenance requiring tank entry cro: TD-58's, 58-0600

(in care) and 55-0670, B-58's 59-2469, 59-2439, 59-2460 and

21

MOY

1

3317

JAMES D. MCLEXY, JR
Colonel, USAF

43d Dep Cdr for Maintenance

80

JAMES D. MCLEXY, JR., COLONEL,

UNCLAS

UNCLASSIFIED

43DCM

43DCM

ROUTINE

50-1021. One (1) KC-135 returning early from AIC Light deployment for fuel leaks not repairable at the forward base. In addition, fifteen (15) pods still require fuel cell repair. Known requirements constitute approximately an 600 man-hour backlog. It is essential that the same depot personnel be utilized since they are now familiar with all personnel, equipment locations, facilities and procedures peculiar to this base, and are highly qualified in repair of major fuel leaks resulting from recent 1090 Mod.

43DCM

2 2

James J. ...
Deputy Commander in Chief, ...
3342

- NOTE: Differences between assigned and available are one (1) five (5) level departure (Jan 1969), one (1) five (5) level (1) return Apr 69 for early out, must be replaced), one five (5) level (1) (Comp 15 Jan). Known gains are:
- One (1) 7-level, APRIL 1969, avail May 69.
- Two (2) 5-level, MAY 1969, avail Jan 69.
- One (1) 5-level, FEB 1969, avail Mar 69.
- One (1) 5-level, MAR 1969, avail Apr 69.
- One (1) 5-level, FEB 1969, avail Mar 69.
- One (1) 5-level, MAY 1969, avail Jan 69.

Known losses are:

- One (1) 5-level early out Jan 69.
- One (1) 5-level, early out Feb 69.

Providing no further ICS/TFY withdrawals occur, an end position of thirteen (13) assigned will be attained in June 1969. In the interim depot personnel are required to accomplish the workload. Estimated military available for the three month assistance period is January 8, February-9 and March 10. Document direct labor for this shop during November was 2259 ME (MILITARY) and 2421 (civilian). Total labor performed by six (6) military and nine (9) civilian personnel operating two (2) twelve (12) hour shifts, six days per week.

JAMES B. MURPHY JR. Col. 43001, 3317
Deputy Commander Unit

Civilians reported 20 December and military continues to operate
some shift schedule but with an increasing number of work stoppages
due to lack of personnel. At this writing, two (2) tank entries are
in progress with six (6) work orders stopped for lack of personnel.
Request re-certification of assistance. Further request team be
available for duty at this station on 2 Jan. 1959. Please advise.

Grounded Hustler Finds New Job

At first glance, it appears Squadron 16 set up a firm to be just another General training schedule, not just mechanics B-59 Hustler work on a 'watch as catch' setting in a corner of the camp arrangement.

The squadron had to re-wire it as most of the wiring was either burned-out or cut. They also took leading gear out of a station of a

successfully supreme flying aircraft, but would not be able to do so until they had substituted it for the aircraft will revert to the leading gear on the aircraft. They put together a team of 43rd Armament and Electronics Maintenance Squadron personnel, 43rd Field Maintenance Squadron personnel, and their own people to make it ready.

Since they started using the aircraft for training purposes, the time required to train unskilled personnel up to a certifiable level has been reduced by about 40 per cent. It used to take about 20 working days, eight to 10 hours per day, to certify a crew, and it now takes only 12 to 13 days.

The squadron has one leading evaluation team to instruct the trainees. These men are the highest qualified personnel available.

When Col. James D. Pigley, 43rd Bombardment Wing commander for maintenance, and Lt. Col. Carlton Mirab, 27th Maintenance Squadron commander, heard the evaluation team's verdict, they had found an answer to an age-old problem in the military--how to train unskilled personnel.

Having their own training aircraft would eliminate the need to tie-up a flying aircraft and would enable the personnel available.



VISUAL CHECK--Sgt. David D. Deiter performs a visual inspection of the pod to insure that it is good, usable condition.

19 NOV 1968

NNNN 10 CFWA645
 011170Z RUCVAAA930 3241706 0000 - RUMTFA
 ZNY 1228
 R 181200Z NOV 68
 FM 2AF BARKSDALE AFB LA
 TO AIG 694/CSUP/DCM
 ZEN/2POYANG/CSUP/DCM/BARKSDALE AFB LA
 AIG 697/DM
 RI

1385/9

430CM-8
 43C-1

UNCLAS DP5A7
 FOR AIG 697 (INFO)
 SUBJ: NORS AND CANN DATA FOR OCTOBER
 THE FOLLOWING IS FURNISHED FOR YOUR INFO.

	B 50		F-4E/D-175		ADM AGY
	NORS	CANN	NORS	CANN	
ALTUS			0.5	.02	
BARKSDALE	3.3	.46	1.1	.07	0.6
BLITHEVILLE	13.1	.76	1.4	.09	0.0
CARSWELL	1.8	.10	2.2	.04	
DISS	5.7	.25	2.1	.18	
GRAND FORKS	7.5	.65	1.0	.54	0.5
KINCHELOF	2.6	.19	1.6	.15	3.0
W. I. SAWYER	4.8	1.40	1.2	.52	3.7

6

MONTH	AMT
JAN	
FEB	
MAR	
APR	
MAY	
JUN	
JUL	
AUG	
SEP	
OCT	
NOV	
DEC	
TOTAL	

PAGE 2 RUCVAAA930 UNCLAS

WORTHSMITH	10.4	.57	2.4	.39		2.1
LOCKBOURNE			0.3	.05		
GRISCOM			2.5	.11		
LITTLE ROCK			2.6	.07		
2AF	5.7	.34	1.7	.15	0.4	2.5
8AF	7.8	.59	4.9	.27	4.4	2.8
15AF	2.6	.53	1.7	.19	1.2	3.2
SAC	4.2	.34	2.3	.14	2.7	3.5
	B-58					
GRISCOM	0.5	.27				
LITTLE ROCK	0.4	.09				
2AF	1.5	.18				
BT						

NNNN

266

18 DEC 1968

UNCLAS DM347
 FOR AIG 697 (INFO)
 SUBJ: NORS AND CANN DATA FOR NOVEMBER
 THE FOLLOWING IS FURNISHED FOR YOUR INFO.

	B-52		B-70/KC-135		ADM	AGM
	NORS	CANN	NORS	CANN		
ALTONS			0.7	.03		
BARKSDALE	1.6	.54	2.6	.17	0.7	
ELY/INWILLE	36.5	.20	2.0	.03	0.2	
CANNON	5.2	.04	1.0	.05		
DYESS	8.0	.58	1.7	.09		
GRANT FORTS	2.5	.22	1.6	.43		0.7
KINCHLOE	19.6	.30	9.2	.17		8.7
K I SAWYER	3.1	.31	2.9	.16		3.3

PAGE 2 RUCVAAA7622 UNCLAS

WURTSMITH	11.4	.61	3.2	.31		3.9
LOCKBOURNE			0.3	.09		
GRISSOM			1.4	.10		
LITTLE ROCK			1.1	.05		
2AF	9.7	.35	2.0	.13	0.4	2.7
8AF	7.8	.75	3.3	.20	3.2	2.7
15AF	2.8	.59	1.5	.20	0.4	0.7
SAC	3.8	.44	2.0	.15	1.8	2.3
B-58						
GRISSOM	2.8	.08				
LITTLE ROCK	1.4	.06				
2AF	2.1	.07				
RT						
7622						

6

AGENCY	ACT	INFO
DCR		
ADM		
COM-1		
COM-2		
COM-3		
COM-4		
COM-5		
COM-6		
COM-7		
COM-8		
COM-9		
COM-10		
COM-11		
COM-12		
COM-13		
COM-14		
COM-15		
COM-16		
COM-17		
COM-18		
COM-19		
COM-20		
COM-21		
COM-22		
COM-23		
COM-24		
COM-25		
COM-26		
COM-27		
COM-28		
COM-29		
COM-30		
COM-31		
COM-32		
COM-33		
COM-34		
COM-35		
COM-36		
COM-37		
COM-38		
COM-39		
COM-40		
COM-41		
COM-42		
COM-43		
COM-44		
COM-45		
COM-46		
COM-47		
COM-48		
COM-49		
COM-50		
COM-51		
COM-52		
COM-53		
COM-54		
COM-55		
COM-56		
COM-57		
COM-58		
COM-59		
COM-60		
COM-61		
COM-62		
COM-63		
COM-64		
COM-65		
COM-66		
COM-67		
COM-68		
COM-69		
COM-70		
COM-71		
COM-72		
COM-73		
COM-74		
COM-75		
COM-76		
COM-77		
COM-78		
COM-79		
COM-80		
COM-81		
COM-82		
COM-83		
COM-84		
COM-85		
COM-86		
COM-87		
COM-88		
COM-89		
COM-90		
COM-91		
COM-92		
COM-93		
COM-94		
COM-95		
COM-96		
COM-97		
COM-98		
COM-99		
COM-100		
SUS		
DATE:		
REPLY BY:		

NNNN

49.

VZCZCFMAR69
RTTUZYUW RUCVAAA5192 0152252-UUUU--RUWTF AA.
ZNR UUUUU

TO ZEN/COMBWBG/CSUP/DCM/BARKSDALE AFB LA

AIG 697/DM

AIG 694/CSUP/DCM

BT

UNCLAS DMSAZ

FOR AIG 697 (INFO)

SUBJ: NORS AND CANN DATA FOR DECEMBER

THE FOLLOWING IS FURNISHED FOR YOUR INFO.

	B-52		EC/KC-135		ADM	AGM
	NORS	CANN	NORS	CANN		NORS
ALTUS			2.1	.00		
BARKSDALE	4.2	.80	1.7	.10	0.0	0.7
BLYTHEVILLE	16.5	.32	0.8	.05	1.3	3.4
CARDWELL	3.7	.02	0.4	.00		
DYESS	3.9	.36	1.3	.22		
GRAND FORKS	2.9	.20	0.5	.08		0.2
KINCHLOX	5.0	.46	9.6	.42		3.9
K J SAWYER	2.0	.29	2.6	.11	0.0	6.3

PAGE 2 RUCVAAA5192 UNCLAS

WORTSMITH	6.5	.48	2.1	.30		1.1
LOCKBOURNE			1.1	.09		
GEORGE			1.9	.09		
WALL			0.7	.05		
2AF	2.6	.43	1.9	.12	0.4	2.5
4AF	4.8	.73	4.6	.37	0.7	2.7
17AF	1.8	.42	2.3	.15	0.1	0.5
SAC	4.0	.36	2.7	.16	0.5	2.1
RSB						
ONTISSON	1.3	.20				
WALL	1.0	.14				
2AF	1.5	.16				

BT
5192

UNCLASSIFIED

58 2005 2 Nov 68

ROUTINE

825TRTATARGOLPBYV LITTLE ROCK AFB ARK

2NE/DJA BARKSDALE AFB LA

INFO: 305NW/303A GRISBORN AFB TX

6250RATARGOLPBYV/DJ LITTLE ROCK AFB ARK (303A)

825TRTATARGOLPBYV/30 LITTLE ROCK AFB ARK (303A)

430
4310
4320
4330.A

UNCLAS 4310.A

Subj: Material C&S Items from 4310 for October 1968

NOTE: TANKER ACFT Material cancellations are in the red for the current month.

AREA	CURRENT MONTH			CUMULATIVE		
	DIVISION	DIVISOR	PERCENT	DIVISION	DIVISOR	PERCENT
TANKER	16	120	11.6	25	551	6.4
AIR ACFT	3	124	2.4	17	511	3.3
WING RATE	90	25329	0.4	573	100856	0.6
GEN RATE	16	207	.08	83	820	.10

NOTE: TANKER ACFT Material cancellations are in the red for the current month.

TANKER	3	86	3.5	6	315	1.9
AIR ACFT	0	74	0	3	279	1.1

8
REV *6*

1

LEONARD S. HARRISON, CMC USAF
MAGIC, Maintenance Analysis

6720

38

R
JAMES F. RICHARD, JR., Colonel, USAF
Deputy Commander for Maintenance

UNCLASSIFIED

	CURRENT MONTH			CUMULATIVE		
WIND RATE	326	12427	2.6	809	52709	1.5
RAIN RATE	6	91	.07	35	209	.09
PART C: TOWER PLOGA						
WIND RATE	16	16	1.0	54	54	1.0
RAIN RATE	15	16	.9375000	52	54	.9625000
OR TIME RATE	15	15	1.0	51	52	.9807692
AIR RATE	14	14	1.0	44	44	1.0
GRAFF	11	11	1.0	43	43	1.0
FOUR NAV	12	14	.8571428	42	50	.8400000
OTHER SYS	15	15	1.0	51	52	.9807692
PLOGA RATE			<u>80.4</u>			<u>77.8</u>

PART D: TOWER PLOGA
NOT ALONG THIS STATION

UNCLASSIFIED

6 DEC 1968 28478

ROUTINE

825STRATAHQDPDIV LITTLE ROCK AFB ARK

2M/10A BARKSDALE AFB LA

305LM/100A GRISSON AFB IND

825STRATAHQDPDIV/10 LITTLE ROCK AFB ARK (100A)

825STRATAHQDPDIV/10 LITTLE ROCK AFB ARK (100A)

430
430
430
430

FORM 4300A

Subj: Material CWS Items from 430W for November 1968

PART A: BOMBER ACFT

AREA	CURRENT MONTH			CUMULATIVE		
	DIVISIB	DIVISOR	PERCENT	DIVISIB	DIVISOR	PERCENT
INT CANK	8	115	7.0	43	606	6.5
AIR ACFT	4	106	3.8	21	617	3.4
WHS RATE	300	25166	1.4	933	126022	0.7
WHS RATE	10	178	.06	93	996	.09

PART B: TANKER AIRCRAFT

INT CANK	0	74	0	6	209	1.5
AIR ACFT	2	69	2.9	5	348	1.4
WHS RATE	105	9953	1.1	914	62712	1.5

1

6720
ERNEST B. HARRISON, C. S., USMC
MOIC, Maintenance Analysis37
JAMES D. RIGLEY, JR., Colonel, USMC
Deputy Commander, Maintenance

UNCLASSIFIED

UNCLASSIFIED

	CURRENT MONTH			CUMULATIVE		
WIND RATE	5	78	.06	40	477	.06
PART C: BOLLER TONCA						
AIR MINT	13	13	1.0	67	67	1.0
AIR RATE	13	13	1.0	65	67	.9701492
ON TIME RATE	13	13	1.0	64	65	.9846153
AIR REGUL	13	13	1.0	57	57	1.0
GRANT	9	9	1.0	52	52	1.0
LONG NAV	13	13	1.0	55	63	.8730150
OTHER CYS	13	13	1.0	64	65	.9846153
PLANN RATE			100.0			82.1

PART D: TANKER TONCA
NOT FLOWN THIS MONTH

Transmission by routine administrative message directed by 2A

Reg 002211Z Apr 68.

(b) (1) (B)



(b) (1) (B)



MEMORANDUM

TO: SAC, [illegible] (43-1000) R

FROM: [illegible] (43-1000)

SUBJECT: [illegible] (43-1000)

[illegible] (43-1000)

[illegible] (43-1000)

[illegible] (43-1000)

GENERAL 430000

Subj: Material Out of Area for 4300 for October 1966.

This message in 3 parts. Part 1. 1-42 Material Cancellations. A rate of 11.6 percent is the highest in this area since the current measurement system was implemented. There were 138 cancellations scheduled and 16 Material Cancellations. Fuel tank leaks were the factors behind 6 of these cancellations with 3 occurring during the last 6 flying days of the month. The aircraft involved were: 2430 on 24 Oct, 1015 on 24 Oct, 26 Oct, 20 Oct and 2430 on 29 Oct. The remaining fuel tank cancellation was 2001 on 10 Oct. A depot assistance team is in place to assist in repairing 1015 and 2430. Three malfunctions that resulted in cancellations were discovered by the aircrew. The aircraft

8
1

ROBERT L. HUBBARD, S-4, USAF
NOSC, Maintenance Analysis

0720

JAMES L. [illegible], S-4, USAF, [illegible],
Deputy Commander, [illegible]

UNCLASSIFIED

UNCLASSIFIED

involved and the malfunctions were high ET on 2453 during takeoff roll on 8 Oct. No airspeed indication on 1019 during take off roll on 9 Oct; lost Search Radar on 2436 during taxi, on 9 Oct. The cancellations on 9 Oct were snowtime sorties. Under normal operations with the 3 hour cancellations criteria, the aircraft could have made a takeoff. The remaining 7 cancellations establish no trend as to malfunction, component or system. Supply was not a contributing factor and the malfunctions were all discovered by ground crew during some phase of maintenance. Part 2. Tanker Cancellations. Three Supply Cancellations on 86 scheduled OAS sorties put this area above standard. Two aircraft were involved. Aft 1467 was NORS and cancelled on 7 and 8 Oct for a Nose Strut. The old strut was scored. Aft 1460 was NORA and cancelled 8 Oct for a flexible fuel hose. Part III. Combined bomber and tanker cancellations for the month was 19 with 9 occurring during the week of 7-13 Oct. An NEST visit during that week could have been a contributing factor.

UNCLASSIFIED

UNCLASSIFIED

Return

6250/MAINTENANCE DIV/DC LITTLE ROCK AFB ARK

20/DNA TADWELL AFB LA

3020/MAINT DIV/DC FT. RUSK

8250/MAINTENANCE DIV/DC LITTLE ROCK AFB ARK (PAC)

8250/MAINTENANCE DIV/DC LITTLE ROCK AFB ARK (PAC)

UNCLAS 430001

Subj: Materiel GT Red Area from 43M for November 1966.

This message is in 4 parts. Part I. 1-58 Materiel Cancellations.

There were 8 cancellations on 115 scheduled G-4 sorties for a rate of 7 percent. Fuel leaks which required tank entry for reworking accounted for 5 of the 8 cancellations. There were 4 aircraft involved and they were: 1015 on 13 Nov; 2455 on 14 Nov; 2440 on 20 and 22 Nov and 2454 on 25 Nov. A depot maintenance team was in place assisting repair. The remaining 3 cancellations were for different causes: 1015 cancelled 1 Nov due to an internal oil leak in Nr 2 engine. 1015 cancelled 14 Nov for extensive maintenance and inspection following an Air Short on 12 Nov. 1015 was not released from alert 15 Nov. Replacement

9
1

6720

JAMES E. HAMILTON, C-1, USAF
MOIC, Maintenance Analysis

47

JAMES D. RIGLEY, JR., Colonel, USAF
Deputy Commander, Maintenance

UNCLASSIFIED

aircraft was used to replace an un scheduled removal of another aircraft for fuel leaks. Part III. B-36 Air Alerts. There were 2 Air Alerts on 106 B-36 sorties for a rate of 3.8 percent. Two alerts were caused by the pressurization system, 1 by the hydraulic system and 1 by the electrical system. The pressurization alert was soft 2446 on 22 Nov. Cabin pressure would climb with altitude. The cabin pressure regulator was defective. Soft 2436 on 19 Nov lost cabin pressure due to a loose coupling on the cold air ducts. The hydraulic system alert was soft 2443 on 12 Nov. The utility system was lost during gear retraction due to a broken line to the left brake shut-off valve. The electrical system alert was soft 1013 on 29 Nov, due to failure of the Nr 3 generator resulting in fluctuating gear packs and cracks in the cockpit. Part III. B-135 Alerts. There were 2 alerts on 69 B-135 sorties for a rate of 2.9 percent. One was caused by the power plant system. Soft 0246 shutdown Nr 1 engine 18 Nov, due to fluctuating oil pressure. The engine was removed and replaced due to 4th carbon seal and Nr 5 bearing support failure. The remaining alert was caused by the hydraulic system. Soft 1470 lost hydraulic quantity 20 Nov, in the right system due to a cracked union on the pressure filter. Part IV. No red areas for the period.

MEMORANDUM

SUBJECT: [Illegible]

DATE: [Illegible]

TIME: [Illegible]

1. [Illegible]

2. [Illegible]

3. [Illegible]

4. [Illegible]

5. [Illegible]

6. [Illegible]

7. [Illegible]

8. [Illegible]

9. [Illegible]

10. [Illegible]

11. [Illegible]

12. [Illegible]

13. [Illegible]

14. [Illegible]

15. [Illegible]

BT

W. H. [Illegible]

[Illegible]

[Illegible]

WLDZCP24300
RUMTFAA/822STRATAEROSPDIV/4320 LITTLE ROCK AFB AR
ZNR 00000

2205

TO RUMTFAA/CSAF ANADAT B
RUMTFAA/822STRATAEROSPDIV/4320 LITTLE ROCK AFB AR
INFO RUCSAAA/SAC/000A

Handwritten:
A/E
1/20/68
DO-1


BT
UNCLAS DDFC

THE RUNWAY AT LITTLE ROCK AFB WILL BE CLOSED FOR MAINTENANCE REPAIRS FROM 1630Z TO 2100Z 4 TO 8 NOV AND 12-13 NOV, AND 1600Z TO 2200Z ON 11 NOV 68. NO EFFECT ON FWO OR TRAINING. RUNWAY CAN BE OPENED IN 5 MINUTES FOR EMERGENCIES. THE LENGTH OF TIME AND PERIODS OF THE DAY WERE ESTABLISHED IN CONSIDERATION OF WEATHER AND TEMPERATURE FACTORS. IMMEDIATE REPAIR ACTION IS REQUIRED BECAUSE THE ASPHALT PLANT COMMENCES INTERMITTENT OPERATION DURING THE LATTER PART OF NOVEMBER AND CONTINUES THIS SPOTTY OPERATION THROUGH THE WINTER MONTHS. APPROPRIATE NOTAMS WILL BE ISSUED BY LITTLE ROCK AFB. THE ABOVE HAS BEEN APPROVED BY MR. HUBBARD, SAC, LITTLE ROCK.

NNNN

SYNTHETIC TRAINING DEVICES OPERATIONAL STATUS AND EVALUATION REPORT											DATE REPORT MADE 31 Oct 1968	CONTROL NO SAC - E2
TO: (Maj Sub Comd Hq) DAF (LO)			INFO TO: Hq SAC (M...) (BOZAG) OFFICE STD, Nebraska 68113					FROM: (Orgn, Comd of Assignment & Location) 43 DEPARTMENT Wing (SCOTS) Little Rock AFB, Ark. 72076				
TYPE & SERIAL NO (Incl maj arch of devices being reported)	STATUS	POWER ON HOURS	CUMU- LATIVE POWER ON	TRAINER HOURS SCHED	TRAINER HOURS UTILIZED	PERCENT TRAINING COMPL	TRAINING HOURS LOST			REMARKS (Continue on 2 x 10 1/2" sheets of paper if more room required.)		
							MAINT	NO SHOW	OTHER			
A	B	C	D	E	F	G	H	I	J	K		
A/F 37A-T13 SN 61620002	A	292	41065	110	106	96	0	0	4	IGTD's 43D3-2-9-500 & 43D3-2-9-501 installed 21 Oct 68 thru 31 Oct 68. Col J--2 hrs lost to broken alert acft; 2 hrs lost to practice alert.		
A/F 37A-T13 SN 61620003	A	376	40493	201	179	89	0	2	20	Col I--2 hrs lost-crew failed to understand latest change to schedule. Col J--12hrs lost to practice alerts-3 hrs lost, crews restricted to alert facility-4 hrs lost to broken alert acft and 1 hr lost to Bomb/Nav trainer malfunction.		
AM/ASQ-T2 SN 61210001	A	365	38858	129	118	91	0	0	11	Col J--6 hrs lost to broken alert acft; 2 hrs lost to practice alert and 3 hrs lost to scheduling error.		
AM/ASQ-T2 SN 61210003	A	381	34463	176	151	85	1	3	21	Col K--1 hr lost-incorrect power supply output. Col I--3hrs lost-crew did not understand latest change to schedule. Col J--12 hrs lost to practice alert; 3 hrs lost crews restricted to alert facility; 6 hrs lost to broken alert acft.		
AM/ASQ-T1 SN 61460001	A	238	24998	120	109	90	0	0	11	Col J--3 hrs lost to broken alert acft. 2 hrs lost to practice alert; 3 hrs lost due to training accomplished in acft and 3 hrs lost to unscheduled briefing.		
AM/ASQ-T1 SN 61460002	A	310	24158	187	163	87	0	2	22	Col I--2 hrs lost-crew failed to understand latest change to schedule. Col J--12 hrs lost to practice alerts; 3 hrs lost crew restricted to alert facility; (continued)		

SYNTHETIC TRAINING DEVICES OPERATIONAL STATUS AND EVALUATION REPORT											date mo) 30 Nov 1968	SAC - E2
TO: (Maj Sub Comd Hq) 2AF (DO 3)			INFO TO: Hq SAC (DO 3)					FROM: (Orig. Comd of Assignment & Location) 43rd Bombardment Wing (POW) Little Rock AFB, Ark 72076				
TYPE & SERIAL NO (Incl maj etch if devices being reported)	STATUS	POWER ON HOURS	COM- LATIVE POWER ON	TRAINER HOURS SCHED	TRAINER HOURS UTILIZED	% SCHED TRAINING COMPL.	TRAINING HOURS LOST			REMARKS (Continue on 3 x 10 1/2" sheets of paper if more room required)		
							MAINT	NO SHOW	OTHER			
A	B	C	D	E	F	G	H	I	J	K		
AN/37A-T13 SN 61620002	A	24	41350	156	146	94	0	0	10	Col J--4hrs lost to scheduling error 3hrs lost to broken alert acct and 3hrs lost to No-Notice testing by C.E.G.		
AN/37A-T13 A SN 61620003	A	291	40724	101	98	97	0	0	3	TGEO's 4303-2-9-960 and 4303-2-9-151 in- stalled 4 Nov 1968 thru 13 Nov 1968. 3hrs lost to scheduling error.		
AN/ASQ-T2 SN 61210001	A	214	39072	94	73	80	3	0	18	Col H--3hrs lost due to start of instal- lation of TGEO 4307-12-3-531. Col J-- 3hrs lost, change in alert crews; 9hrs lost to scheduling error; 3hrs lost to No-Notice testing by C.E.G.; 3hrs lost to practice alert.		
AN/ASQ-T2 SN 61210003	A	301	34764	125	119	95	3	0	3	Col H--3hrs lost in changing from EMO to Western XI plate in BK-500. Col J-- 3hrs lost to scheduling error.		
AN/ASQ-T1 SN 61460001	A	255	24353	144	131	91	0	0	13	Col J--7hrs lost to scheduling error; 3hrs lost to practice alert; 3hrs lost to No-Notice testing by C.E.G.		
AN/ASQ-T1 SN 61460002	A	243	24401	126	117	94	0	0	9	Col J--3hrs lost to scheduling; 3hrs lost to broken alert acct.		
P-3-A Instrument Trainer SN 50000560	A	23	12173	16	16	100	0	0	0			
C-11-C Instrument Trainer SN 50000185	A	0	22040	0	0	0	0	0	0			


 ROBERT R. REYNOLDS, LtCol, USAF
 Chief, Operations and Training Division
 43rd Bombardment Wing

SYNTHETIC TRAINING DEVICES OPERATIONAL STATUS AND EVALUATION REPORT

TYPE & SERIAL NO (Do not include or include this number)		STATUS	POWER ON HOURS	ORIG LATV POSITION	TRAINER HOURS SCHED	TRAINER HOURS ACTUAL	TRAINER HOURS REMAINING	TRAINING HOURS LOST			REMARKS
A	B	C	D	E	F	G	H	I	J	K	L
AN/ASQ-111 SN 61670002	A	312	1007	142	158	65	0	0	24	Col J-3 was lost to scheduled training, then lost to flight change. One lost to unavailability. One lost to alert.	
AN/ASQ-113 SN 61520003	A	314	1037	175	167	95	0	0	8	Col J-3 was lost to unavailability in absence of crew member, practice alert.	
AN/ASQ-12 SN 61210001	A	326	1008	116	104	90	4	0	8	Col J-3 was lost to flight change. One lost to unavailability. One lost to alert.	
AN/ASQ-12 SN 61210003	A	230	1494	94	85	90	0	0	9	Col J-3 was lost to unavailability.	
AN/ASQ-11 SN 61460001	A	391	2464	135	110	80	0	0	25	Col J-3 was lost to unavailability. One lost to flight schedule. Lost to unavailability during practice alert, then lost to EIA. One lost to unavailability.	
AN/ASQ-71 SN 61460002	A	253	2464	147	138	93	0	0	9	Col J-3 was lost to unavailability. One lost to alert, 1.5 hrs lost to unavailability. 3 hrs lost to unavailability.	
TSA Instrument Trainer SN 50000560	A	25	12198	16	16	100	0	0	0		
C18G Instrument Trainer SN 50000185	A	22	22062	14	14	100	0	0	0		

43rd B/ Troop Housing
 October - December 1968

Squadron	No. Rooms Assigned	No. Living in Rooms	Average Per Room
(End of October)			
HS	30	64	2.1
FMS	77	180	2.4
O/S	116	220	1.9
M/S	38	74	1.9
AE/S	44	60	1.4
(End of November)			
HS	30	64	2.1
FMS	71	167	2.3
O/S	116	213	1.8
M/S	38	78	2.0
AE/S	45	94	2.1
(End of December)			
HS	30	64	2.1
FMS	67	156	2.4
O/S	116	214	1.8
M/S	38	79	2.0
AE/S	45	94	2.1

"An Accurate Extract"

Jason R. Kappas
 JASON R. KAPPAS
 1st Lt, USAF

DEPARTMENT OF THE AIR FORCE
 HEADQUARTERS, 825TH COMBAT SUPPORT GROUP (SAC)
 LITTLE ROCK AIR FORCE BASE - JACKSONVILLE, ARKANSAS 72076

16 January 1969

MINUTES OF THE BASE FAMILY HOUSING MANAGEMENT COUNCIL - LITTLE ROCK AFB, ARKANSAS

1. The LITTLE ROCK AIR FORCE BASE FAMILY HOUSING MANAGEMENT COUNCIL convened in accordance with SACR 85-10 at 1000 hours, 16 January 1969.

a. Members Present:

Capt Martin H. Levin, 825th Svc Sq (ESV), Acting Chairman
 Capt Norman L. Blakley, 825th Sec Pol Sq (BCSP)
 Capt W.E. Burleson, 825th Cmbt Spt Gp (BCR), Authorized Representative
 Capt C.R. Consent, 825th Cmbt Spt Gp (BFR), Authorized Representative
 Capt Joe R. Lamport, 825th Hq Sq (EJA), Authorized Representative
 W.J. Hutchins, DAFG, 825th Sup Sq (CSUP), Authorized Representative
 Jerry F. Ryan, DAFG, 825th Civ Engr Sq (BCE), Authorized Representative
 Milton P. LaVasque, DAFG, 825th Svc Sq (LQVH), Recorder

b. Members Absent:

Colonel Theodore R. Dale, 825th Cmbt Spt Gp (EDC)
 Colonel Walter J. Schweiger, Jr., 825th Cmbt Spt Gp (BP)
 Captain James C. Threet, 825th Trans Sq (TSTM)

c. Others Present:

TSgt James Camille, 825th Civ Engr Sq (BCEP)
 Patricia S. Bentley, 825th Svc Sq (ESVH)

2. Old Business:

a. Mr. Ryan of CES reported that in-house capability for garbage collection could not be obtained. He suggested that the present contract for this service be rewritten to emphasize in detail the requirements that must be met by the contractor. CES personnel will continue to exercise close supervision over these services.

b. The Base Housing Office has assumed the responsibility of maintaining a current listing of available Housing Contract Cleaners. This responsibility will be limited to reference purposes only and made available to occupants for ready reference as they schedule termination of quarters. The Base Housing Office will not encourage or discourage the use of Contract Cleaners, nor will Base Housing personnel recommend anyone for this service. Personnel desiring this information will be referred to the available listings, informed of minimum/maximum charges as determined by the Installation Commander, and given a blank contract form for use by the individual and cleaner, if desired. Utilization of these services will be the sole responsibility and choice of each individual.

c. Captain Blakley of Security Police reported that in accordance with the provisions of AFR 125-14, E/Sup-1, housing occupants may park boats and/or trailers in their driveways or carports provided there is available space for privately-owned vehicles. It was emphasized that there is a designated area for utilization of housing personnel specifically for the purpose of parking boats, trailers, etc. which would alleviate the necessity of using driveways and carports for this purpose.

3. New Business:

a. Housing Occupancy Rate as of 31 December 1968: 99.6%

b. Assignments and Terminations:

(1) Housing Status:

<u>Type of Quarters:</u>	<u>Available:</u>	<u>Assigned:</u>	<u>Reassigned:</u>	<u>Waiting:</u>
Senior Grade, 4-ER	12	12	0	0
Field Grade, 3-ER	171	171	3	3
Company Grade, 3-ER	344	342	12	0
Company Grade, 2-ER	86	86	5	9
Enlisted, 3-ER	552	449	21	0
Enlisted, 2-ER	370	359	20	0

(2) Number of On-Base Moves: 113

(3) Number Quarters Declared Excess: 0

(4) Number Families of Eligible Sponsors Currently Overseas Occupying Government Quarters: 6

(5) Number DOD Civilians Occupying Government Quarters: 0

(6) Number Ineligibles Occupying Government Quarters: 1

(7) Number Families of Ineligible Sponsors Currently Overseas Occupying Government Quarters: 0

(8) Total Vacant Unit Days Chargeable to Base Housing: 92

(9) Average Unit Days Per Vacant Unit Chargeable to Base Housing: 158

(10) Number Quarters Vacated During the Month of December: 58

c. Programming of Maintenance, Repair, Alteration, and Construction:

(1) Service Calls (Housing & Base) - 1684

(a) Received (Housing Only): 1394

(b) Completed (Housing Only): 839

- (2) Units in CE Hands on 31 December 1968: 4
- (3) Units Processed by CES During the Month of December: 59
- (4) Total Vacant Unit Days Chargeable to CES in December: 64
- (5) Average Unit Days Per Vacant Unit Chargeable to CES: 1.08
- (6) Longest Period of Time CES had Any One Unit During the Month of December: 10 Days (179 Pennsylvania Drive)

d. Housing Bench Stock Fill Rate: 76.6%

e. Occupant Care and Maintenance of Structures and Adjacent Grounds: (See paragraph 3j for Contracts/Projects in progress and programmed).

f. Summary of P-721 and P-722 Funds as of 31 December 1968:

(1) P-721 Funds:		2nd Qtr	Spent To	% of Annual	
EE:	Description:	Allot:	Date:	Program:	
392.00	Labor	\$ 26,900	\$ 15,200	\$ 15,187	56.5 %
480.XX	Utilities	458,600	215,900	203,594	44.4
533.30	Refuse Collection	30,400	30,385	30,375	99.9
569.40	Furniture Maintenance	3,200	3,000	1,447	27.8
592.30	Rentals	9,900	5,200	5,129	51.8
609.00	Supplies	3,400	3,300	3,239	60.0
	Sub-Total:	\$ 536,400	\$ 272,985	\$ 258,971	48.3 %
(2) P-722 Funds:					
392.00	Labor	\$ 156,900	\$ 83,000	\$ 84,861	54.1 %
521.XX	Projects	110,877	110,877	110,826	99.9
529.XX	Projects	5,986	5,986	4,110	68.7
569.40	Appliance Maintenance	3,000	500	0	-0-
609.00	Supplies	192,000	94,486	75,667	39.4
628.00	Equipment	13,400	13,400	13,395	100.0
	Sub-Total:	\$ 481,163	\$ 310,249	\$ 268,849	59.9 %
	TOTAL:	\$1,018,563	\$ 583,234	\$ 527,820	53.6 %

g. Preparation of All Reports Pertaining to Family Housing: The Quarterly Housing Report was submitted as of 31 December 1968. The next Quarterly Housing Report will be due as of 31 March 1969. The Semi-Annual World-Wide Housing Report will be submitted in January 1969.

h. Calculation of Housing Requirements:

(1) Known Enlisted Gains: -0-

(2) Known Enlisted Losses: 11

(3) Known Officer Gains: 12

(4) Known Officer Losses: 8

i. Control and Issue of Furniture and Equipment:

(1) Number of Terminal Inspections Required: 58

(2) Number of Terminal Inspections Completed: 58

j. Family Housing Programs:

(1) LRK 12-8, Roof Repairs - Approximately 78% complete as of 31 December 1968.

(2) LRK 10-8, Painting of Exteriors of Capahart Quarters - This contract was reported to be approximately 26% complete on 31 December 1968. This contract has been temporarily closed, but will reopen 15 March 1969, weather permitting.

(3) W/O #9-1244, Installation of Yard Lamps for Fride Quarters - To be accomplished as soon as materials are received (4 lamps available now).

(4) LRK 70-8, Sidewalk Construction - Approximately 98% complete on 31 December 1968.

(5) W/O #9-1435, Replacement of Street Signs - Materials 50% complete; scheduled for completion in FY-70.

4. Meeting adjourned at 1110 hours. The next meeting of the BASE FAMILY HOUSING MANAGEMENT COUNCIL will convene at 1000 hours on Thursday, 20 February 1969, in the Blue Room of the Officers Open Mess.

Milton P. LaVasque
 MILTON P. LA VASQUE, DAFC
 Recorder

Martin H. Levin
 MARTIN H. LEVIN, Captain, USAF
 Acting Chairman

DISTRIBUTION

1 - 43C	3 - 2AF (DM3E)
1 - SU	6 - 2AF (DPSN)
2 - BSV	1 - BC
1 - 43DCM	1 - EDC
5 - BSVH	1 - 308C
10 - 1 Ea Member	

APPROVED DISAPPROVED

McLerie P. Zumwalt
 MCLELIE P. ZUMWALT, Colonel, USAF
 Commander

Crew S-45 Wins Bomb Wing Trophy

Crew S-45 has won the 43rd Bombardment Wing's "Bomb Wing Trophy" for July 1 to Dec. 31, 1968. Col. Sherwin G. Desens, 43rd BW commander, pre-

sented the trophy to the crew Jan. 8 on the flight line.

Crew S-45 members are Majors Rodney B. Henney, pilot, and Paul A. Johnson, navigator; and Capt. Alan

D. McKenzie, defensive systems operator.

The award is based upon a crew rating system which uses average points per mission as the criteria.

The crew established the highest points per mission average, and also set a wing record for the most points credited for one sortie.

In addition, during this

rating period, Crew S-45 was subjected to Second Air Force Combat Evaluation Group testing and received a rating of "Highly Qualified."

Colonel Desens stated, "This award is a significant achievement as there are more than 50 hand picked, highly professional and competitive crews within the 43rd Bombardment Wing."

Crew S-45 is assigned to the 43rd BW Combat Crew Training School. Major Henney is the most experienced instructor pilot in the school, having accumulated more than 1,300 hours in the General Dynamics B-58 Hustler. He graduated his first

student in 1963.

During one of his earlier training flights a flight control malfunction developed which could have resulted in the loss of a multi-million dollar aircraft. Major Henney was awarded the Air Medal for the safe recovery of his aircraft.

Major Johnson has been assigned to the 43rd BW for six years. He has served with Major Henney for more than two years.


Captain McKenzie was assigned to the wing in 1964 from Lincoln AFB, Neb., where he served as wing penetration aids officer. He has been a member of Crew S-45 for more than one and one-half years.

Two Majors Decorated For SEA Duty

Maj. Prince H. Harris, 70th Aerial Refueling Squadron, received two Silver Stars, the Distinguished Flying Cross, and the ninth Oak Leaf Cluster to the Air Medal; and Maj. Leslie P. McConnell, 70th AREFS, the Distinguished Flying Cross in ceremonies yesterday morning.

Brig. Gen. James E. Hill, 825th Strategic Aerospace Division commander, made the presentations.

Major Harris was awarded the Silver Stars for similar actions as a T-28 fighter pilot in Southeast Asia. On Dec. 11, 1967, he flew a night armed reconnaissance mission of heavily defended hostile lines of communication in a renovated T-28 trainer. He made repeated passes into the focal point



Major Harris

of antiaircraft and automatic weapons positions. Despite heavy fire, strong winds, and rugged terrain, Major Harris destroyed three hostile vehicles and silenced two gun positions.

On Nov. 18, 1967, Major Harris was engaged in conducting a night armed re-

connaissance mission in an extremely mountainous and heavily fortified area when he detected a hostile forces convoy. He attacked the convoy, destroying and burning five heavily loaded supply vehicles.

The DFC went to Major Harris for the close air support he provided friendly ground forces on Feb. 13, 1968.

The ninth OLC to the Air Medal was awarded Major Harris for his achievements in aerial flight from Aug. 27, 1967 to June 3, 1968.

Major McConnell was awarded the DFC for his participation as an EB-66 aircraft commander in aerial flight over North Vietnam. On Dec. 20, 1967, he flew his unarmed electronic



Major McConnell

countermeasures aircraft on a jamming support mission against radar directed anti-aircraft weapons and surface-to-air missiles which threatened a B-52 combat force. The B-52s were attacking hostile troop concentrations near the Demilitarized Zone.

Aerial Heroics In SEA Bring DFC To Thomas

Captain Thomas, Thomas, 1967. The aerial briefing session, received the Distinguished Flying Cross Friday for aerial heroics in Southeast Asia.

Captain Thomas served as an RF-4C pilot in SEA. On Jan. 29, 1968, he flew an unarmed and unescorted night reconnaissance mission to obtain photographic coverage for bomb assess-

ment of a target area in the western theater.

The citation accompanying the award reads: "In spite of formidable terrain barriers, and intense and accurate hostile fire, Captain Thomas skillfully guided his aircraft through these hazards and obtained complete coverage of his assigned target."

His accomplishment enabled friendly forces to pinpoint hostile gun positions, and map and determine the serviceability of unfriendly supply routes.

Captain Thomas also received his thirteenth OLC to the Air Medal for service in SEA from July 2, 1967 to April 29.



..... Captain Thomas